


District I
1625 N. French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised March 17, 1999
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nMLB 1214553770 OPERATOR Initial Report Final Report

Name of Company Devon Energy	6137	Contact Tracy Kidd, Production Foreman
Address P. O. Box 250 Artesia, NM 88211		Telephone No. 575-513-0628
Facility Name Cotton Draw 65 SWD		Facility Type Salt Water Disposal

Surface Owner	Mineral Owner	Lease No. 042565-010
---------------	---------------	----------------------

LOCATION OF RELEASE

30-015-10843

Unit Letter	Section	Township	Range	Feet from the 1980	North/South Line	Feet from the 1980	East/West Line	County
65	2	25S	31E	1980	North	1980	East	Eddy

NATURE OF RELEASE

Type of Release 79bbls Produced Water / 1bbls Oil	Volume of Release 80 bbls	Volume Recovered 80bbls
Source of Release Gun barrel overflow	Date and Hour of Occurrence 4/22/12, 5:33 PM	Date and Hour of Discovery 4/22/12, 5:33 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos / BLM & Mike Bratcher / OCD	
By Whom?	Date and Hour 4/23/12, 10:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* At the Cotton Draw 65, the fill line to the water tanks from the gun barrel plugged, causing an overflow of 79 bbls of produced water and 1 bbl oil.		
Describe Area Affected and Cleanup Action Taken.* At the Cotton Draw 65, the fill line to the water tanks from the gun barrel plugged, causing an overflow of 79 bbls of produced water and 1 bbl oil. All was within a lined containment and all liquid was recovered. Ordered vacuum truck, steamed cleaned tanks and containment.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: Gracie C. Bustamante	OIL CONSERVATION DIVISION	
Printed Name: Gracie C. Bustamante	Signed By <u>Mike Bratcher</u> Approved by District Supervisor:	
Title: Admin Field Support	Approval Date: MAY 24 2012	Expiration Date: N/A
Date: Phone: (575) 746-5561	Conditions of Approval: N/A	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Final
2RP-1127