

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

MAY 04 2012

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company BOPCO, L.P.	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: Hat Mesa State 31-32 Battery	Facility Type E&P
Surface Owner: State of N.M.	Mineral Owner State of N.M.
Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	31	20S	33E					Lea

Latitude N 32.534822 Longitude W 103.700502

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 5 bbls crude oil	Volume Recovered: 0
Source of Release: A 4" truck load line	Date and Hour of Occurrence Un-known	Date and Hour of Discovery 4/18/12 13:20 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* <p style="text-align: right;">GW @ 70'</p>		

Describe Cause of Problem and Remedial Action Taken.* Connections on the 4" truck load have been leaking over a period of time. The tank battery is currently undergoing a complete re-build of the process lines.

Describe Area Affected and Cleanup Action Taken.* An area covering approximately 200 sq.ft. inside the tank battery earthen containment has been affected by the release. Most of the soil has been excavated and is stockpiled on-site. Soil samples have been collected from the excavated area and are being analyzed for TPH, BTEX and Chlorides. A Remediation plan will be developed and submitted prior to moving the material off-site. The spill will be remediated following the NMOCD guidelines for spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	ENV SPECIALIST: Approved by District Supervisor: <i>Jeff Lebing</i>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: 5/21/12	Expiration Date: 7/21/12
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: SUBMIT FINAL	Attached <input type="checkbox"/> IRP-5-12-2812
Date: 5/2/12 Phone: 432-556-8730	C-141 BY 7/21/12	

* Attach Additional Sheets If Necessary

JUN 14 2012