

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nMLB1215334891*

**OPERATOR**  Initial Report  Final Report

Name of Company BOPCO, L.P. <i>260737</i>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: James Ranch Unit #112-H Pumping Well	Facility Type E&P
Surface Owner: State of N.M.	Mineral Owner State of N.M. Lease No. <del>NM 02953-C</del>

**LOCATION OF RELEASE** *AAE# 30-015-36722*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	36	22S	30E					Eddy

Latitude 32.34270 Longitude W 103.82626

**NATURE OF RELEASE**

Type of Release: Crude oil and produced water	Volume of Release: 15 bbls crude oil and 15 bbls produced water	Volume Recovered: 10 bbls total fluid
Source of Release: Pump Jack Well Head	Date and Hour of Occurrence 4/30/12 Time unknown	Date and Hour of Discovery 4/30/12 9:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency # 104	
By Whom? Tony Savoie	Date and Hour 4/30/12 2:49 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*	<div style="border: 2px solid black; padding: 5px; width: fit-content; margin: auto;"> <p style="margin: 0;"><b>RECEIVED</b></p> <p style="margin: 0;">MAY 04 2012</p> <p style="margin: 0;"><b>NMOCD ARTESIA</b></p> </div>	

Describe Cause of Problem and Remedial Action Taken.\* The well pressured up and blew out the stuffing box packing. The packing was replaced and the pressure problem was corrected.

Describe Area Affected and Cleanup Action Taken.\* An area covering approximately 1800 sq.ft. on the caliche well pad was affected by the release. All of the free standing fluid was recovered with a vacuum truck. The stained area on the well pad was left intact; a remediation crew will start sampling the impacted area on 5/7/12 to determine the vertical extent of the release. The spill will be remediated following the NMOCD guidelines for spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by District Supervisor <i>M. L. Brennan</i>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: <b>JUN 01 2012</b>	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	Attached <input type="checkbox"/>
Date: 5/2/12 Phone: 432-556-8730	<i>7/1/2012</i>	<i>2PA-1141</i>

\* Attach Additional Sheets If Necessary