

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**HOBBS OCD**

**JUN 14 2012**

**RECEIVED**

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Jeremy Haass
Address 104 S. 4 <sup>TH</sup> Street	Telephone No. 575-748-1471	
Facility Name Patsy State Unit #2	API Number 30-005-27934	Facility Type Pumping Unit

Surface Owner State	Mineral Owner State	Lease No. V-5739
------------------------	------------------------	---------------------

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	11	12S	31E	660	South	660	West	Chaves

Latitude 33.28612 Longitude 103.79807

**NATURE OF RELEASE**

Type of Release Crude Oil & Produced Water	Volume of Release 30 B/O & 24 B/PW	Volume Recovered 15 B/O & 6 B/PW
Source of Release Tank	Date and Hour of Occurrence 6/12/2012 AM	Date and Hour of Discovery 6/12/2012 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking, NMOCD I	
By Whom? Jeremy Haass, Yates Petroleum Corporation	Date and Hour 6/12/2011 AM (email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Hole in bottom of tank. Well shut off, called vacuum truck.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 40' X 40', all in bermed battery. Vacuum truck called to pick up remaining oil and produced water, impacted soils to be scraped up and taken to an NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX, Chlorides will be run for documentation. If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted. <b>Depth to Ground Water: 50-99' (approximately 85', Section 03-T12S-R31E, per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: &gt;1000', SITE RANKING IS 10.</b>		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jeremy Haass	Approved by District Supervisor:	<b>Accepted for Record Only</b> 06/14/12
Title: Environmental Regulatory Agent	Approval Date:	Expiration Date:
E-mail Address: jhaass@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Tuesday, June 12, 2012 Phone: 575-748-1471	2RP-	IRP-6-12-2824

\* Attach Additional Sheets If Necessary

DSM 12721 879D

JUN 20 2012