

District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
811 S First St , Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15 29 NMAC.

**Release Notification and Corrective Action**

*nJMW1217341655*

**OPERATOR**  Initial Report  Final Report

Name of Company Lime Rock Resources II-A, L.P. 217558 Contact Michael Barrett

Address 1111 Bagby St Suite 4600 Houston, TX 77002 Telephone No. 575-623-8424

Facility Name West Red Lake Unit #44 Facility Type WIW

Surface Owner BLM Mineral Owner BLM API No. 30-015-28444

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	5	18S	27E	840'	FSL	1750'	FWL	Eddy

Latitude 32.77161 Longitude 104.30283

**NATURE OF RELEASE**

Type of Release <u>Produced Water</u>	Volume of Release <u>49 bbls</u>	Volume Recovered <u>12 bbls</u>
Source of Release <u>2" Injection Line Split @ Wellhead</u>	Date and Hour of Occurrence <u>06/07/2012 am</u>	Date and Hour of Discovery <u>06/07/2012 @ 8 am</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Mike Bratcher / NMOCD and Jim Amos / BLM via voicemail</u>	
By Whom? <u>Michael Barrett</u>	Date and Hour <u>6/8/12 @ 3 pm</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**  
JUN 19 2012  
NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.\*  
2" Injection Line Split @ Wellhead.  
Shut off water flow, repaired line & bermed flow path.

Describe Area Affected and Cleanup Action Taken.\*  
Packed Caliche & Rock.  
Talon LPE has been contracted to do site assessment and formulate a work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	<b>OIL CONSERVATION DIVISION</b> Signed By <i>[Signature]</i>	
Printed Name: <u>Michael Barrett</u>	Approved by Environmental Specialist:	
Title: <u>Production Supervisor</u>	Approval Date: <b>JUN 21 2012</b>	Expiration Date:
E-mail Address: <u>mbarrett@limerockresources.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>

Date: 06/08/2012 Phone: 575-623-8424

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**  
7/21/12

**2RP-1183**

\* Attach Additional Sheets If Necessary