


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011  
Submit to the appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*JMW 1217347760*

*OCRID# 27184* OPERATOR

Initial Report  Final Report

Name of Company ALAMO PERMIAN RESOURCES, LLC	Contact STEVEN MASTIN
Address 415 W. WALL ST. SUITE 500	Telephone No. 432-557-5847
Facility Name EMPIRE J FEDERAL #3	Facility Type WELL
Surface Owner FEDERAL	Mineral Owner FEDERAL
API No. 30-015-00169	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	1	18S	26E	2304	N	330	E	EDDY

Latitude 32.7723 Longitude -104.32915

**NATURE OF RELEASE**

Type of Release: Oil and Water	Volume of Release: <b>EST</b> 3 bbls Oil, 11 bbls Water	Volume Recovered: 2 bbls Oil
Source of Release: Backside casing valve.	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 6/14/2012
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Stewart	
By Whom? Jennifer Van Curen, BLM	Date and Hour 6/14/2012	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken *		
Cause of problem: Discharge from backside casing valve. Remedial Action Taken: Vacuum trucks dispatched to suck up standing fluid.		
Describe Area Affected and Cleanup Action Taken.*		
Localized area around wellsite, vacuum trucks picked up 2 bbls of standing oil. Scraping and proper disposal of remaining fluid.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Tom Fulvi</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: TOM FULVI	Approved by Environmental Specialist:	Signed By: <i>Mike Stewart</i>
Title: REGULATORY AFFAIRS COORDINATOR	Approval Date: <b>JUN 21 2012</b>	Expiration Date:
E-mail Address: tfulvi@alamoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/14/2012 Phone: 432-664-7659		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

7/21/12

*2RP-1184*

**Bratcher, Mike, EMNRD**

---

**From:** Tom Fulvi [tfulvi@alamoresources.com]  
**Sent:** Thursday, June 14, 2012 2:13 PM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** C 141  
**Attachments:** EMPIRE J FED 3 20120614.pdf

Mike,

Attached is a C 141 for a spill today on the Empire J Federal well #3.

Thanks,

Tom Fulvi

Alamo Resources  
415 West Wall St., Suite 500  
Midland, TX 79701  
Office 432-897-0673  
Cell 432-556-0184  
Fax 432-686-8454