

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

n JMW 12180 48947

OPERATOR

Initial Report Final Report

Name of Company BOPCO, L.P. <i>260737</i>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: Poker Lake Unit Pierce Canyon 5 State No. 1H	Facility Type E&P

Surface Owner State of NM	Mineral Owner State of NM	Lease No. <i>API 30-016-36998</i>
---------------------------	---------------------------	-----------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	5	25S	30E					Eddy

Latitude N 32.215518 Longitude W 103.894893 ← *FOR*

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 10 Bbbls of Produced water and 15 Bbbls crude oil	Volume Recovered: None
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence 5/25/12 Time approximately 10:00 a.m.	Date and Hour of Discovery 5/25/12 11:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104 and State Land Office Andrew Kramer	
By Whom? Tony Savoie	Date and Hour 5/25/12 NMOCD at 11:40 a.m. SLO at 11:52 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The flow line developed a leak due to internal corrosion. A temporary repair clamp was placed on the pipe. One joint of pipe was replaced on 5/30/12.

Describe Area Affected and Cleanup Action Taken.* Approximately 675 sq.ft. of caliche road and approximately 480 sq. ft. of pasture land. All of the released fluid soaked into the ground. The remediation will comply with the NMOCD and BLM requirements for spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor:	Signed By: <i>Mike Benavente</i>
Title: Waste Mgmt. & Remediation Specialist	Approval Date: JUN 28 2012	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/22/12	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

7/28/12

