

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

AMCB 1217228658
OPERATOR Initial Report Final Report
 Name of Company BOPCO, L.P. 260737 Contact Tony Savoie
 Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 432-556-8730
 Facility Name Poker Lake Unit Well #154 Facility Type E&P
 Surface Owner Federal Mineral Owner Federal Lease No. APR#

LOCATION OF RELEASE

Unit Letter J	Section 6	Township 23S 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------------------------	--------------	---------------	------------------	---------------	----------------	----------------

30-015-31686

Latitude N 32.244462 Longitude W 103.920312

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 10 Bbls of Produced water and 5 Bbls crude oil	Volume Recovered: None
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence 5/21/12 Time unknown	Date and Hour of Discovery 5/21/12 8:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.* The flow line developed a leak due to external corrosion. A temporary repair clamp was placed on the pipe.

Describe Area Affected and Cleanup Action Taken.* Approximately 720 sq.ft. of caliche road and approximately 600 sq. ft. of pasture land. All of the released fluid soaked into the ground. The remediation will comply with the NMOCD and BLM requirements for spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor Signed By: <u>[Signature]</u>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: <u>JUN 20 2012</u>	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/3/12	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary



2RP-1175
 Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**
7/20/2012