

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Southern Union Gas Services	Contact	Rose Slade
Address	801 S. Loop 464, Monahans, TX 79756	Telephone No.	432-940-5147
Facility Name	Line 4A	Facility Type	Natural Gas Pipeline

Surface Owner	Crawford Ranch	Lease No.	30-025-38822
---------------	----------------	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	30	24S	37E					Lea

Latitude 32 degrees 11.352' North **Longitude** 103 degrees 12.553' West

NATURE OF RELEASE

Type of Release	Natural Gas, Crude Oil and Produced Water	Volume of Release	20 BBLS	Volume Recovered	None
Source of Release	10 inch Natural Gas Pipeline	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	June 27, 2012 - 0830 hours
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			


If a Watercourse was Impacted, Describe Fully.*

GW@75'

Describe Cause of Problem and Remedial Action Taken.*
A ten (10)-inch low pressure natural gas pipeline developed a leak, resulting in a release of natural gas, crude oil and produced water. During initial response activities the pipeline was shut-in to mitigate the release. Following initial response activities, the affected pipeline segment will be replaced with 10 inch poly line and returned to service.

Describe Area Affected and Cleanup Action Taken.*
An area of pasture land measuring approximately 5,400 square feet was affected by airborne liquids. An area of pasture land measuring approximately 1,320 square feet was affected by liquids flowing from the release point. The release will be remediated according to NMOCD regulatory guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Rose L. Slade	Approved by: ENV SPECIALIST:  District Supervisor		
Title: EHS Compliance Specialist	Approval Date: 7/2/12	Expiration Date: 9/2/12	
E-mail Address: rose.slade@sug.com	Conditions of Approval: SUBMIT FINAL C-141 BY 9/2/12		Attached <input type="checkbox"/> IRP-7-12-2835
Date: June 28, 2012	Phone: 432-940-5147		

* Attach Additional Sheets If Necessary