


District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr. Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NMLB 121674727 OPERATOR Initial Report Final Report

Name of Company <u>Lime Rock Resources II-A, LP 277558</u>	Contact <u>Michael Barrett</u>
Address <u>1111 Bagby St Suite 4600 Houston, Tx 77002</u>	Telephone No. <u>575-623-8424</u>
Facility Name <u>West Red Lake Unit #60</u>	Facility Type <u>Battery</u>

Surface Owner <u>BLM</u>	Mineral Owner <u>BLM</u>	Lease No. <u>API # 30-015-28781</u>
--------------------------	--------------------------	-------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	5	18S	27E	50'	FSL	1930'	FWL	Eddy

Latitude 32.76944 Longitude 104.30223

NATURE OF RELEASE

Type of Release <u>Produced Water</u>	Volume of Release <u>82 bbls</u>	Volume Recovered <u>0 bbls</u>
Source of Release <u>1/4" needle valve on filter pot @ wellhead</u>	Date and Hour of Occurrence <u>5/28/12 am</u>	Date and Hour of Discovery <u>5/28/12 @ 8 am</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Voice mail to OCD & BLM</u>	
By Whom? <u>Michael Barrett w/ LRR</u>	Date and Hour <u>5/28/12 @ 6pm</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
1/4" needle valve blew out of filter pot (threads eroded). Isolated well, plan to sample and submit work plan.

Describe Area Affected and Cleanup Action Taken.*
Rock and Caliche. Talon LPE has been contracted to do a site assessment and formulate a work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>[Signature]</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Michael Barrett</u>	Signed By <u>[Signature]</u> Approved by District Supervisor:	
Title: <u>Production Supervisor</u>	Approval Date: <u>JUN 13 2012</u>	Expiration Date:
E-mail Address: <u>mbarrett@limerockresources.com</u>	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date: <u>5/31/12</u> Phone: <u>575-623-8424</u>	<u>7/13/2012</u>	

* Attach Additional Sheets If Necessary

PROPOSAL NOT LATER THAN:
7/13/2012

2RA-1168