

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

MAR 23 2012

RECEIVED

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

X Initial Report X Final Report

Name of Company: New Mexico Salt Water Disposal Co.	Contact: William Palmer, Manager
Address: P.O. Box 1518 Roswell, NM 88202	Telephone No.: 575-396 5391
Facility Name: Station #8	Facility Type: Battery

Surface Owner:	Mineral Owner	Lease No.:
----------------	---------------	------------

**LOCATION OF RELEASE**

CONTINENTAL STATE OOI  
NEAREST WELL API # 30.025-22551

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	8	10S	34E	2640	North	2000	East	LEA

Latitude: Longitude:

**NATURE OF RELEASE**



Type of Release: produce water	Volume of Release: 100	Volume Recovered: 100
Source of Release: overflow line on tank	Date and Hour of Occurrence: between 500 PM 3/10/2012 & 10:25AM 3/11/2012	Date and Hour of Discovery: 10:25 AM 3/11/2012
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken. Switch that operates water transfer pump at dump station inadvertently turned on. More water transferred to Station #8 than could be handled, in present condition. Switch will be enclosed and secured.

Describe Area Affected and Cleanup Action Taken. Water was completely enclosed in polyethylene lined and bermed area. All water removed from bermed area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: William V. Palmer	ENV SPECIALIST: Approved by District Supervisor:	
Title: Manager	Approval Date: 3/6/12	Expiration Date: —
E-mail Address: wpalmer@read-stevens.com	Conditions of Approval: —	Attached <input type="checkbox"/>
Date: 3/21/2012 Phone: 575-396 5391		IRP-8-12-2843

\* Attach Additional Sheets If Necessary

AUG 7 2012