

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1219334159

OPERATOR

Initial Report Final Report

Name of Company BOPCO, L.P. <i>260737</i>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name Poker Lake Unit Well #128-123	Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No. <i>APZ*</i>
-----------------------	-----------------------	-----------------------

LOCATION OF RELEASE

30-015-28526

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	22	24S	31E	1980	South	1980	West	Eddy

Latitude N 32.200969 Longitude W 103.767830

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 20 Bbls of Produced water and 6 Bbls crude oil	Volume Recovered: 10 bbls total fluid mostly water
Source of Release: Pumping wellhead	Date and Hour of Occurrence: 5/28/12 Time unknown	Date and Hour of Discovery: 5/28/12 8:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 and BLM Jim Amos	
By Whom? Tony Savoie	Date and Hour 5/29/12 8:17 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Fluid was discovered coming from an open "I" valve on the wellhead and a broken gauge. The well was shut in the valves closed.

Describe Area Affected and Cleanup Action Taken.* Approximately 2600 sq.ft. of caliche pad and approximately 60 sq. ft. of pasture land was affected by the spill from the open valve. Approximately 4000 sq.ft. of pasture land was misted with oil and water from the broken gauge. A vacuum truck removed approximately 10 bbls of fluid at the time it was discovered. The remediation of the produced water and crude oil will be in compliance with the NMOCD and BLM guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor:	Signed By <i>Mike Brannon</i>
Title: Waste Mgmt. & Remediation Specialist	Approval Date: JUL 11 2012	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/22/12	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

8/11/2012

2RP-1203

RECEIVED
JUN 26 2012
NMOCD ARTESIA