

District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nJMW 1219345739*

**OPERATOR**

Initial Report  Final Report

Name of Company BOPCO, L.P. <i>260737</i>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: Poker Lake Unit Delaware C SWD Battery	Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No 891000303F <i>API#</i>
-----------------------	-----------------------	---------------------------------

*Poker Lake Unit #153*

**LOCATION OF RELEASE**

*30-015-31412*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	6	24S	30E					Eddy

Latitude N 32.248850 Longitude W 103.919067

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release: 25 bbls of produced water	Volume Recovered: None
Source of Release: Produced water storage tank	Date and Hour of Occurrence 5/30/12, Hour unknown	Date and Hour of Discovery 5/30/12 8:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104 and Jim Amos with the BLM	
By Whom? Tony Savoie	Date and Hour 6/1/12, NMOCD at 11:41 a.m. BLM at 11:45 a.m. The report was delayed due to a medical situation with T.S.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* A pipe fitting on the discharge line from the SWD pump broke, the pipe connection was replaced the same day.

Describe Area Affected and Cleanup Action Taken.. Approximately 1960 sq.ft. of pasture land was impacted west of the tank battery, this area has had several flow line spills in the same area that the release covered. All of the fluid soaked into the ground before it could be recovered. A remediation plan will be developed in accordance with the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by District Supervisor:	Signed By <i>Mike Brannon</i>
Title: Waste Mgmt. & Remediation Specialist	Approval Date: <b>JUL 11 2012</b>	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/24/12	Phone: 432-556-8730	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

8/11/12

*2RP-1205*

