

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

nJMW 1219352653

**OPERATOR**

Initial Report  Final Report

Name of Company BOPCO, L.P.	260237	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 432-556-8730
Facility Name: Indian Flats Bass Federal #1 SWD		Facility Type: E&P

Surface Owner Federal	Mineral Owner Federal	Lease No. LC-067144 <del>ATZ</del>
-----------------------	-----------------------	------------------------------------

Indian Flats Bass Fed #1

**LOCATION OF RELEASE**

30-015-24968

Unit Letter J	Section 35	Township 21S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.433905 Longitude W 104.055425

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release: 80 bbls	Volume Recovered: 20 bbls
Source of Release: A salt water transfer pump.	Date and Hour of Occurrence 5/25/12 time unknown	Date and Hour of Discovery 5/25/12 9:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Tony Savoie	Date and Hour 5/25/12 11:40 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* A gauge broke on the pump, water was sprayed outside the containment area on the caliche pad and road at the facility. The gauge was replaced.

Describe Area Affected and Cleanup Action Taken.\*The released fluid affected approximately 5,000 sq. ft. area around the pump, lease road and caliche well pad. The free standing fluid was picked up with a vacuum truck. The release is in the same location as previous spills of 2/8/12 and 5/23/12. An air rotary rig was used to determine the vertical extent of the first release. A rig will be re-scheduled to delineate the recent spills. The Site remediation for the produced water will follow the NMOCD guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie		Approved by District Supervisor: Signed By	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: 11 2012	Expiration Date:	
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 6/24/12	Phone: 432-556-8730		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**

8/11/12

2RP-1209

