

District I
1625 N French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1219528557 OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: Poker Lake Unit 213 SWD	Facility Type: Salt Water Disposal Tank Battery
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-33859	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	18	24S	30E					Eddy

Latitude: N 32.212384 Longitude: W 103.914812

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 60 bbls	Volume Recovered 10 bbls
Source of Release 3" Poly Line	Date and Hour of Occurrence: 6/23/12 Approximately 11:00 p.m.	Date and Hour of Discovery: 6/23/12 Approximately 11:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104	
By Whom? Tony Savoie	Date and Hour 6/24/12 11:15 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
JUL 09 2012
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A transport truck owned by Horizon Trucking ran over the S.W. corner of the 0 perm containment breaking a 3" poly line. The water transfer pump was shut down by the night pumper. The broken line and fitting were repaired the next day.

Describe Area Affected and Cleanup Action Taken.*

Approximately 4050 sq.ft. of caliche pad and road along with approximately 6900 sq. ft. of pasture land was affected by the release. The water standing on the caliche pad area was removed with a vacuum truck. All of the fluid released into the pasture soaked into the ground. The spill area was reviewed with the BLM on 6/27/12. A remediation plan will be submitted along with the BLM recommendation.


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Signed By <i>Mike Brannon</i>	
Title: Waste Mgmt. and Remediation Specialist	Approved by Environmental Specialist:	Approval Date: JUL 13 2012
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Expiration Date:
Date: 7/9/12 Phone: 432-556-8730	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

8/13/12

2RP-1221




Data use subject to license.

© DeLorme Topo North America™ 9

www.delorme.com



Scale 1 25,000



1" = 2,083.3 ft

Data Zoom 13-0