


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

nJMW1219538987 OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO SWD #104	Facility Type	Salt Water Disposal

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-25864
					Closest well location

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
S	F	26S	28E					Eddy

Latitude 32 03.534 Longitude 104 04.620

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	15bbbs	Volume Recovered	14bbbs
Source of Release	Check valve on transfer pump	Date and Hour of Occurrence	06/24/2012	Date and Hour of Discovery	06/24/2012 7:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A check valve on the transfer pump had a 1/4" plug that had rusted out allowing for the release of fluid. The plug has been replaced on the check valve.					
Describe Area Affected and Cleanup Action Taken.*					
Initially roughly 15bbbs were released and we were able to recover 14bbbs with a vacuum truck. The entire release was completely contained inside the lined facility walls. We have removed any contaminated gravel from the facility and replaced it with fresh gravel. The facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By
Title:	HSE Coordinator	Approval Date:	JUL 13 2012
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	07/12/2012	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-212-2399		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

8/13/12

2RP-1225

## Bratcher, Mike, EMNRD

---

**From:** Joshua Russo [jrusso@concho.com]  
**Sent:** Thursday, July 12, 2012 7:44 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** C-141 Initial/Final Report - SRO SWD #104  
**Attachments:** SRO SWD #104 -- DATE OR RELEASE -- 06-24-2012.pdf

Mr. Bratcher,

Please see attached a C-141 Initial/Final Report for a release that occurred at our SRO SWD #104. This is a lined facility.

Thank you,

### **Joshua Russo**

HSE Coordinator  
550 W. Texas Ave, Suite 100  
Midland, Texas 79701  
Phone: (432) 683-7443  
Cell: (432) 212-2399  
[jrusso@conchoresources.com](mailto:jrusso@conchoresources.com)



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.