

RECEIVED

FEB 28 2012

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

NMCB 1030754436 OPERATOR Initial Report Final Report

Name of Company COG Operating LLC	Contact Pat Ellis
Address 550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No. (432) 230-0077
Facility Name GJ West Coop Unit #7	Facility Type Flowline

Surface Owner: State	Mineral Owner	Lease No. B-255 (API#) 30-015-03170
----------------------	---------------	--

LOCATION OF RELEASE




Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	28	17S	29E					Eddy

Latitude 32 48.380 Longitude 104 04.374

NATURE OF RELEASE

Type of Release: Produced Fluid	Volume of Release: 10 bbls	Volume Recovered: 8 bbls
Source of Release: Steel Flowline	Date and Hour of Occurrence: 09/04/2010	Date and Hour of Discovery: 09/04/2010 4:00p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Josh Russo	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The steel flowline developed a weak spot and eventually ruptured causing this release. The steel flowline will be replaced with a new poly flowline.		
Describe Area Affected and Cleanup Action Taken.* Tetra Tech personal inspected the site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report and submitted it to the NMOCD for review.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez (Agent In COG)	Signed By:  Approved by District Supervisor:	
Title: Project Manager	Approval Date: AUG 13 2012	Expiration Date: N/A
E-mail Address: ike.tavarez@TetraTech.com	Conditions of Approval: N/A	Attached <input type="checkbox"/> 2RP-456
Date: 2-13-12 Phone: (432) 682-4559		

* Attach Additional Sheets If Necessary