

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**RECEIVED**  
AUG 17 2012  
NMOCD ARTESIA

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nJMW 1223639425

Name of Company SM ENERGY COMPANY 154903		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address 3300 N "A" ST BLDG 7-200 MIDLAND, TX 79705		Contact VICKIE MARTINEZ		
Facility Name ESDU 6 30-015-25385		Telephone No. (432)688-1709		
		Facility Type WELL		
Surface Owner BUREAU OF LAND MANAGEMENT / Mineral Owner BUREAU OF LAND MANAGEMENT / API No. NMNM101361X				

**LOCATION OF RELEASE**



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	24	18S	31E	890	NORTH	990	EAST	EDDY

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release PRODUCED WATER	Volume of Release 20 BBLs	Volume Recovered 15 BBLs
Source of Release 3" POLYETHYLENE FLOWLINE	Date and Hour of Occurrence 8/12/12 6:00 AM	Hour of Discovery SAME
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? JIM AMOS WITH BLM	
By Whom? BILL HEARNE	Date and Hour 8/12/12 2:53 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* 3" POLYETHYLENE FLOWLINE LEAK IN BUTT WELD. CUT OFF BAD SECTION OF LINE, RE-DRESSED ENDS AND WELDED PIPE BACK TOGETHER. SM ENERGY WILL BE TURNING THIS OVER TO TETRA TECH FOR FURTHER EVALUATION.		
Describe Area Affected and Cleanup Action Taken.* SPILL AREA: 40'X30' = 1200 SQ FT		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: VICKIE MARTINEZ	Approved by Environmental Specialist: Signed By 	
Title: ENGINEER TECH II	Approval Date: <b>AUG 22 2012</b>	Expiration Date:
E-mail Address: VMARTINEZ@SM-ENERGY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/15/2012 Phone: (432)688-1709		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

9/22/12

2RP-1257