

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1223641037

Name of Company: BOPCO, L.P. 260737		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Tony Savoie			
Facility Name: Remuda Basin Battery #1 Water Transfer Line		Telephone No. 575-887-7329			
Approximately 1250 ft. East of the battery.		Facility Type: Exploration and Production			

Surface Owner: State of N.M.	Mineral Owner: State of N.M.	API No. 30-015-03691
------------------------------	------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	24	23S	29E					Eddy

Latitude: N 32.288222 Longitude: W 103.932289

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 10 Bbls	Volume Recovered: None
Source of Release: 3" poly line	Date and Hour of Occurrence: 7/26/12 at approximately 9:00 a.m.	Date and Hour of Discovery: 7/26/12 10:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
AUG 20 2012
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The 3" poly line split, the bad section of pipe was replaced.

Describe Area Affected and Cleanup Action Taken.*
Approximately 1800 sq.ft. of pasture was lightly misted at the release point, the fluid traveled down a caliche road, then exited the road into the pasture. Approximately 600 sq.ft. of road and approximately 960 sq.ft. of pasture was affected by the run-off areas. The area was reviewed prior to the release date; it was noted on 4/18/12 that there had been several reports of trucks dumping produced water on the road from the tank battery to Rawhide road. The affected area in the pasture will be remediated in accordance to the NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: Signed By <i>White</i>	
Title: Waste Management and Remediation Specialist	Approval Date: AUG 22 2012	Expiration Date:
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/15/12 Phone: 432-556-8730		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
Sept. 22, 2012**

2RP-1258