

HOBBS OCD

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

OCT 25 2012

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report  Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Airbonita 12 Federal #2H	Facility Type	Poly Flowline

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-025-40179
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	12	22S	32E					Lea

Latitude 32 24.003 Longitude 103 37.592

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	10bbls	Volume Recovered	0bbls
Source of Release	Poly flowline	Date and Hour of Occurrence	10/10/2012	Date and Hour of Discovery	10/10/2012 12:00 p.m.

Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?
-----------------------------	--	------------------

By Whom?	Date and Hour
----------	---------------


Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.
----------------------------	---	---

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A poly flowline released fluid into the pasture adjacent to the pad location. The line has been fused and returned to service.

Describe Area Affected and Cleanup Action Taken.\*  
Initially 10bbls of produced water were released from the poly flowline and we were unable to recover any fluid. The spill area in the pasture measured roughly 40' x 70'. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Josh Russo	Approved by District Supervisor:	 Environmental Specialist
Title:	Senior Environmental Coordinator	Approval Date:	10/26/12
E-mail Address:	jrusso@concho.com	Expiration Date:	12/26/12
Date:	10/25/2012	Phone:	432-212-2399
		Conditions of Approval:	SUBMIT FINAL C-141 BY 12/26/12
		Attached	<input type="checkbox"/>
		IRP - 10-12-2860	

\* Attach Additional Sheets If Necessary