

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1230354745

OPERATOR Initial Report Final Report

Name of Company OXY USA Inc. <i>16696</i>	Contact Leslie V. Moreno
Address 1017 W. Stanolind Rd.	Telephone No. (575) 397-8247
Facility Name Pure Gold B Federal #004	Facility Type Battery

Surface Owner	Mineral Owner	Lease No. API 30-015-27238
---------------	---------------	-----------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	20	23S	31E	660	S	660	E	Eddy


Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Vent	Volume of Release 500 MCF	Volume Recovered 0
Source of Release Temp. Vent	Date and Hour of Occurrence 7/26/11 @ 2400 hrs to 7/26/11 @ 1200 hrs	Date and Hour of Discovery 7/26/11 @ 0700 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher via e-mail	
By Whom? Leslie V. Moreno, HES Administrative Assistant	Date and Hour 7/29/11 @ 11:18 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse n/a	

If a Watercourse was Impacted, Describe Fully.* **n/a**

Describe Cause of Problem and Remedial Action Taken.* **OXY began venting at the Pure Gold B-4 Battery on 7/26/11 due to DCP shut down for repairs at their Pure Gold compressor.**



Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie V. Moreno</i>	OIL CONSERVATION DIVISION	
Printed Name: Leslie V. Moreno	Approved by District Supervisor.	
Title: HES Administrative Assistant	Approval Date:	Expiration Date:
E-mail Address: Leslie_Moreno@oxy.com	Conditions of Approval:	
Date: 8/12/2011 Phone: (575) 397-8247	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1370

Moreno, Leslie V (Office Team)

From: Moreno, Leslie V (Office Team)
Sent: Friday, July 29, 2011 11:18 AM
To: 'Mike.Bratcher@state.nm.us'
Subject: Venting - Pure Gold B-4 Battery, 7/26/11

Mr. Bratcher,

We began venting at the Pure Gold B-4 Battery on 7/26/11 – DCP shut in their Pure Gold compressor for repairs, this lasted 12 hours and we vented 500 MCF. C-141's to follow within the next weeks.

Thank you!

Leslie V. Moreno
HES Administrative Assistant
OXY Permian
1017 W. Stanolind Rd.
Office: (575) 397-8247
Cell: (575) 605-5100
Fax: (575) 397-8234