

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nJMW1230355791*

Name of Company <b>OXY USA Inc.</b>		Contact <b>Leslie V. Moreno</b>	<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address <b>1017 W. Stanolind Rd.</b> <i>16690</i>		Telephone No. <b>(575) 397-8247</b>		
Facility Name <b>Goodnight 27 #1</b>		Facility Type <b>Production Battery</b>		
Surface Owner	Mineral Owner	Lease No. <b>API 30-015-22157</b>		

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	27	23S	29E	660	S	198	W	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_


**NATURE OF RELEASE**

Type of Release <b>Temp. Flare</b>	Volume of Release <b>100 MCF</b>	Volume Recovered <b>0</b>
Source of Release <b>Flare</b>	Date and Hour of Occurrence <b>8/12/11 @ 2400 hrs to 8/12/11 @ 1200 hrs</b>	Date and Hour of Discovery <b>8/12/11 @ 0600 hrs</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mike Bratcher</b>	
By Whom? <b>Leslie V. Moreno, HES Administrative Assistant</b>	Date and Hour <b>8/17/11 @ 3:36 pm</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	

If a Watercourse was Impacted, Describe Fully.\* **N/A**

Describe Cause of Problem and Remedial Action Taken.\* **Oxy began flaring due to DCP unexpected compressor shut down.**

Describe Area Affected and Cleanup Action Taken.\* **N/A**



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie V. Moreno</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Leslie V. Moreno</b>	Approved by District Supervisor:	Signed By: <i>Mike Bratcher</i>
Title: <b>HES Administrative Assistant</b>	Approval Date: <b>OCT 29 2012</b>	Expiration Date: <i>N/A</i>
E-mail Address: <b>Leslie_Moreno@oxy.com</b>	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>
Date: <b>9/20/11</b>	Phone: <b>(575) 397-8247</b>	

\* Attach Additional Sheets If Necessary

Accepted for record  
NMOCD

*2RP-1371*

## **Moreno, Leslie V (Office Team )**

---

**From:** Moreno, Leslie V (Office Team )  
**Sent:** Wednesday, August 17, 2011 3:36 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Moreno, Leslie V (Office Team )  
**Subject:** Venting - CYPRESS 34 #1 & GOODNIGHT 27 #1 BATTERY

Hi Mr. Bratcher,

OXY began venting a the Cypress 34 #1 (200 MCF) and the Goodnight 27 #1 battery (100 MCF) due to DCP unexpected Compressor Shut Down. C-141's to follow.

Thank you!!

Leslie V. Moreno  
HES Administrative Assistant  
OXY Permian  
1017 W. Stanolind Rd.  
Office: (575) 397-8247  
Cell: (575) 605-5100  
Fax: (575) 397-8234