

HOBBS OCD

NOV 06 2012

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
**RECEIVED**  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report

Final Report

<b>Name of Company:</b> Chevron USA	<b>Contact:</b> Bradley Blevins
<b>Address:</b> 1616 West Bender, Hobbs, NM 88240	<b>Telephone No.:</b> (575) 391-1462 ext. 86424
<b>Facility Name:</b> Quail Queen Unit 10	<b>Facility Type:</b> Flow Line
<b>Surface Owner:</b> State of New Mexico	<b>Mineral Owner:</b>
<b>API No.:</b> 30-025-26348	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	11	19S	34E	1980	North	660	East	Lea

**Latitude:** N32° 40' 40.62" **Longitude:** W103° 31' 34.40"

**NATURE OF RELEASE**

<b>Type of Release:</b> Oil and produced water	<b>Volume of Release:</b> ~30-bbbls	<b>Volume Recovered:</b> ~18-bbbls
<b>Source of Release:</b> Flow line	<b>Date and Hour of Occurrence:</b> 10/13/12	<b>Date and Hour of Discovery:</b> 10/13/12 @ 09:30
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Geoff LeKing, OCD; James Amos, BLM	
<b>By Whom?</b> Bradley Blevins	<b>Date and Hour:</b> 10/13/12	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse:</b>	
<b>Depth to water:</b> ~ 85 ft		
<b>If a Watercourse was Impacted, Describe Fully:</b> * Not Applicable		
<b>Describe Cause of Problem and Remedial Action Taken.*</b> A flow line ruptured releasing ~30 bbbls oil and produced water with ~18 bbbls recovered. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area.		
<b>Describe Area Affected and Cleanup Action Taken.*</b> Approximately 5,800 square feet of area was affected by the release of oil and produced water. Visibly stained soil was excavated and hauled away for disposal at a state approved facility. Soil samples were collected and submitted to Cardinal Laboratories for testing. Having received acceptable results and NMOCD approval, the affected area has been backfilled, and returned to proper conditions.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
<b>Signature:</b> <i>Bradley Blevins</i>	<b>OIL CONSERVATION DIVISION</b> <i>Geoff LeKing</i> Environmental Specialist	
<b>Printed Name:</b> Bradley Blevins	<b>Approved by District Supervisor:</b>	
<b>Title:</b> EH & S Field Specialist	<b>Approval Date:</b> 11/7/12	<b>Expiration Date:</b> —
<b>E-mail Address:</b> bradley.blevins@chk.com	<b>Conditions of Approval:</b> —	<b>Attached</b> <input type="checkbox"/>
<b>Date:</b> 11-6-12 <b>Phone:</b> (575) 391-1462 ext. 86424	IRF-11-12-2864	

\* Attach Additional Sheets If Necessary