

HOBBS OCD

NOV 08 2012

Form C-141  
Revised October 10, 2003

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report  Final Report

Name of Company <b>ConocoPhillips Company</b>	Contact <b>John W. Gates</b>
Address <b>3300 North A St. Bldg 6, Midland, TX 79705-5406</b>	Telephone No. <b>505.391.3158</b>
Facility Name <b>MCA Station 4</b>	Facility Type <b>Oil and Gas</b>

Surface Owner <b>Federal</b>	Mineral Owner <b>Federal</b>	Lease No
------------------------------	------------------------------	----------

LOCATION OF RELEASE

NEAREST WELL MCA UNIT #126  
API #30-025-12709

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	26	17	32					Lea

Latitude 37.178181"N Longitude 96.054581"W

NATURE OF RELEASE



Type of Release <b>Produced Water</b>	Volume of Release 5.4bbl (0oil, 5.4water)	Volume Recovered (0oil, 1.5water)
Source of Release <b>Sump Tank ran over due to sump pump failure</b>	Date and Hour of Occurrence <b>11/4/12 @ 1200 HRS</b>	Date and Hour of Discovery <b>11/5/12 @ 0800 HRS</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
**GW @ 49'**

Describe Cause of Problem and Remedial Action Taken.\*  
The release originated from a sump tank that ran over due to the sump pump locking up. Upon discovery the MSO isolated the leak and reported the pump failure to mechanic and HSE

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is an ~111' X 75' X .5" area of caliche location. The MSO called for a vacuum truck and ~1.5 bbls of water was recovered. The spill area will be remediated in accordance with BLM & NMOCD guidelines

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION  Environmental Specialist	
Printed Name: <b>John W. Gates</b>	Approved by District Supervisor:	
Title: <b>HSER Lead</b>	Approval Date: <b>11/09/12</b>	Expiration Date: <b>01/09/13</b>
E-mail Address: <b>John.W.Gates@conocophillips.com</b>	Conditions of Approval: <b>SUBMIT FINAL</b>	Attached <input type="checkbox"/>
Date: <b>11/08/12</b> Phone: <b>505.391.3158</b>	<b>C-141 BY 01/09/13</b>	<b>IRP-11-12-2865</b>

• Attach Additional Sheets If Necessary

NOV 14 2012