


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011  
Submit 1 Copy to appropriate District Office in NMOC D ARTESIA with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*JMW1224938010* OPERATOR  Initial Report  Final Report

Name of Company: Judah Oil, LLC <i>245372</i>	Contact: James B. Campanella
Address: PO Box 568, Artesia, NM 88211	Telephone No.: 575-748-5488
Facility Name: Cedar Lake Unloading Station	Facility Type: SWD
Surface Owner: BLM	Mineral Owner: BLM
API No. <i>30-015-32265</i>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	29	17S	31E					Eddy

Latitude N 32.65109200 Longitude W -103.13899000

**NATURE OF RELEASE**

Type of Release: Oil and Produced Water	Volume of Release: 942 bbls Oil & 11,910 bbls PW	Volume Recovered: Not Known
Source of Release: tank Facility	Date and Hour of Occurrence: 8/19/2012 @ 12:03 am	Date and Hour of Discovery: 8/19/2012 @ 12:03 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? 12:03 am called 911, 12:14 am OCD, 12:19 am Jim Amos/BLM—12:50 am talked to Jim Amos, 12:33 am CVE	
By Whom? James Campanella	Date and Hour: see above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* Cedar Lake SWD Unloading Station was struck by lightning. All tanks were burnt causing a release of 11,910 barrels of produced water and 942 barrels of oil. All fluids released were within the below grade containment at the Cedar Lake SWD Unloading Station which was lined. A vacuum truck was called to recover the standing fluids

Describe Area Affected and Cleanup Action Taken.\* Talon/LPE was contracted for the correction of this release. The impacted areas from this release were excavated to a depth of 2-4 feet deep. The impacted soil was transported to a NMOCD approved solid waste disposal facility and analytical testing was completed. The excavation was backfilled to grade using new material and the below containment was reconstructed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: James B. Campanella	Approved by Environmental Specialist:	
Title: Member Manager	Approval Date: <b>DEC 05 2012</b>	Expiration Date: <i>N/A</i>
E-mail Address: jbc@judahoil.com	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>
Date: 11/19/2012 Phone: 575-746-1280		

\* Attach Additional Sheets If Necessary

*2RA-1273*