


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nJM/W/1232050706

OPERATOR Initial Report Final Report

Name of Company: Oxy USA Inc <i>157984</i>	Contact Chris Jones
Address 1502 W. Commerce Drive	Telephone No. 575-449-3337
Facility Name: Eeyore 34 State #1	Facility Type: Producing Well
Surface Owner	Mineral Owner
API No. 3001539383	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	34	17 S	28 E	738	N	488	E	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 103 BBLS	Volume Recovered: 100 BBLS
Source of Release: Frac Tank	Date and Hour of Occurrence: 11/11/12 9:00 pm	Date and Hour of Discovery: 11/11/12 9:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- NMOCD Jim Amos- BLM	
By Whom? Chris Jones	Date and Hour: 11/13/12 1:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A valve was properly shut on a frac tank and released produced water on the well pad. A vac truck was on site and able to get the majority of it cleaned up. It was isolated to an area on the well pad. SESI will do some initial sampling and we will come up with a plan for clean up based off of that for proposal.		
Describe Area Affected and Cleanup Action Taken.*		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Chris Jones	Approved by Environmental Specialist: Signed By <i>Mike Bratcher</i>	
Title: HES Specialist	Approval Date: NOV 15 2012	Expiration Date:
E-mail Address: Christopher_Jones@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: _____ Phone: 575-449-3337		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: Dec. 15th 2012**

2RP-1405

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com
Sent: Wednesday, November 14, 2012 8:02 AM
To: Bratcher, Mike, EMNRD; jamos@blm.gov
Cc: ballen@sesi-nm.com
Subject: Eeyore 34 #1
Attachments: Document.pdf

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com
Sent: Tuesday, November 13, 2012 12:44 PM
To: Bratcher, Mike, EMNRD; jamos@blm.gov; ballen@sesi-nm.com
Subject: Eeyore 34 St 1

This is to inform you that Oxy had a spill on 11/11/12 at the EYORE 34 STATE 001.

SESI WILL BE DOING SOME INITIAL DELINEATION A C141 TO FOLLOW.

VOLUME OF SPILL IS 103 BBLS PRODUCED WATER 100 BBLS WAS RECOVERED SURFACE AREA IS 50 X 40 FT FURTHER REMEDIATION REQUIRED WEATHER CONDITIONS COOL SURFACE OWNER STATE LAND SURFACE LEASEE OXY REGULATORY LEASE # API 300 153 9383<tel:300%20153%209383> COUNTY AND STATE EDDY, NEW MEXICO LEGAL DESCRIPTION SEC A 24 T17S R28E DRIVING DIRECTIONS AT THE INTERSECTION OF HWY 82 AND COUNTY ROAD<x-apple-data-detectors://6> 360 GO SOUTH FOR A COUPLE 100 YDS ON THE 1ST DIRT ROAD TO THE LEFT GO 1/4 MILE DOWN ROAD TO LOCATION

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle