

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
NOV 14 2012
NMOCD ARTESIA DISTRICT

Form C-141
Revised October 10, 2003
2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NJM W 1232055488 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Willow State	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-28880



LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	16	17S	31E					Eddy

Latitude 32 49.693 Longitude 103 52.411

NATURE OF RELEASE

Type of Release	Produced water w/ skim oil	Volume of Release	200bbls	Volume Recovered	190bbls
Source of Release	Water pump swedge	Date and Hour of Occurrence	11/07/2012	Date and Hour of Discovery	11/07/2012 7:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-OCD			
By Whom?	Michelle Mullins	Date and Hour	11/07/2012 12:12 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* The swedge at the water pump parted at the threads allowing the release of fluid into the facility. The swedge has been replaced.					
Describe Area Affected and Cleanup Action Taken.* Initially 200bbls were released from the swedge at the water pump and we were able to recover 190bbls with vacuum trucks. All free fluid has been recovered. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By 
Title:	Senior Environmental Coordinator	Approval Date:	NOV 15 2012
E-mail Address:	jrusso@concho.com	Expiration Date:	
Date:	11/14/2012	Phone:	432-212-2399
		Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-1408

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**
Dec. 15, 2012

Bratcher, Mike, EMNRD

From: Joshua Russo <jrusso@concho.com>
Sent: Wednesday, November 14, 2012 1:12 PM
To: Bratcher, Mike, EMNRD
Cc: Ike Tavarez (ike.tavarez@tetrattech.com); Robert Grubbs (Robert.Grubbs@tetrattech.com); Tom Franklin (tom.k.franklin@tetrattech.com)
Subject: C-141 Initial Report - Willow State Tank Battery
Attachments: WILLOW STATE TANK BATTERY -- DATE OF RELEASE -- 11-07-2012.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for the Willow State Tank Battery. We plan to assess the spill area timely.

Thank you,

Joshua Russo

Sr. Environmental Coordinator

432.683.7443 (main)

432.685.4381 (direct)

432.212.2399 (cell)

jrusso@concho.com

Mailing Address:

One Concho Center

600 W. Illinios Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.