

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DEC 11 2012

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	BC Federal #10	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#) 30-025-37021	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	19	17S	32E					Lea

Latitude 32.82284 Longitude 103.80913

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	20bbbs	Volume Recovered	18bbbs
Source of Release	4" line to scrubber	Date and Hour of Occurrence	12/04/2012	Date and Hour of Discovery	12/04/2012 8:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A hole developed in the 4" line going to the scrubber inside the BC Federal #10 Tank Battery. An emergency clamp has been installed on the line as a temporary repair.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbbs were released from the 4" line and we were able to recover 18bbbs with a vacuum truck. The entire release has been contained inside the facility. All free fluid has been recovered and the surface of the spill area has been removed and hauled to disposal. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD/BLM for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:	<p style="text-align: center;">OIL CONSERVATION DIVISION</p> <p style="text-align: center;"><i>Jeffrey Yelking</i> Approved by District Supervisor: Environmental Specialist</p>				
Printed Name:					
Title:	Senior Environmental Coordinator	Approval Date:	12/11/12	Expiration Date:	02/11/13
E-mail Address:	jrusso@concho.com	Conditions of Approval: SUBMIT FINAL			Attached <input type="checkbox"/>
Date:	12/11/2012	Phone:	432-212-2399	C-141 BY 02/11/13 IRP-12-12-2882	

* Attach Additional Sheets If Necessary

DEC 11 2012