


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

n. JMW 1225550869

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amanda Trujillo
Address 104 S. 4 TH Street		Telephone No. 575-748-1471
Facility Name Amole AMM State #4	API Number 30-015-28542	Facility Type Well
		Order Number 2RP- 1282
Surface Owner State	Mineral Owner State	Lease No. LG - 864

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	16	19S	25E	1980	South	660	East	EDDY

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 7 bbls Oil 10 bbls PW	Volume Recovered 0
Source of Release Broken Flowline	Date and Hour of Occurrence 8/23/2012 - PM	Date and Hour of Discovery 8/23/2012 - PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD/Artesia	
By Whom? Amanda Trujillo - Yates Petroleum Corporation	Date and Hour 8/28/2012 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Broken Flowline caused a release to flow into pasture. Well was shut in and repairs made. Vacuum truck was dispatched to control incident.		
Describe Area Affected and Cleanup Action Taken.* An approximate size of 8' x 40' was impacted. The impacted area is located South of the well on the edge of the well pad. Soil from the pooling areas was excavated and placed in plastic and will be disposed of at an NMOCD approved facility. Vertical and horizontal delineation samples will taken and analysis ran for TPH and BTEX once all contaminated material has been removed. Depth to Ground Water: >50' (approx. 95', per New Mexico Chevron/Texaco Trend Map); Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 10.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By <i>Mike Bratcher</i>	
Title: Environmental Scientist	Approved by District Supervisor:	
E-mail Address: atrujillo@yatespetroleum.com	Approval Date: DEC 14 2012	Expiration Date: <i>N/A</i>
Date: Wednesday, December 12, 2012	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>
Phone: 575-748-4310	<i>Final</i>	

2RP-1282

* Attach Additional Sheets If Necessary