

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*nJMW 1235332604* OPERATOR  Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Remuda Basin Battery #1 Well Location	Facility Type: Exploration and Production
Surface Owner: State of N.M.	Mineral Owner: State of N.M.
API No. 30-015-03691	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	24	23S	29E					Eddy

Latitude: N 32.288041 Longitude: W 103.936333

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release: Unknown	Volume Recovered: None
Source of Release: Unknown truck unauthorized release	Date and Hour of Occurrence: Date and hour unknown	Date and Hour of Discovery: 11/26/12 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour 11/26/12 at 10:22 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The spill was caused by an un-authorized release on the well pad location.		
Describe Area Affected and Cleanup Action Taken.* Well pad location, drilling reserve pit, and pasture land. No clean has been initiated pending investigation at the site. The affected area in the pasture will be remediated in accordance to the NMOCD guidelines.		

**RECEIVED**  
DEC 17 2012  
**NMOCD ARTESIA**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist:	Signed By: <i>Mike Brennan</i>
Title: Waste Management and Remediation Specialist	Approval Date: <b>DEC 18 2012</b>	Expiration Date:
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/17/12	Phone: 432-556-8730	

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: January 18<sup>th</sup>, 2013**

*2RP-1458*

\* Attach Additional Sheets If Necessary