


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW 1301854979

Name of Company		COG OPERATING LLC <i>229137</i>	OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address		600 West Illinois Avenue, Midland, TX 79701	Contact	Pat Ellis		
Facility Name		SRO 102 SWD	Telephone No.	432-230-0077		
Surface Owner		State	Facility Type	SWD		
Mineral Owner				Lease No. (API#) 30-015-21398		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	26S	28E					Eddy

Latitude 32 02.657 Longitude 104 05.431

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	320bbbls	Volume Recovered	280bbbls
Source of Release	Header	Date and Hour of Occurrence	12/31/2012	Date and Hour of Discovery	12/31/2012 11:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Michelle Mullins	Date and Hour	01/02/2013 9:00 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
The inlet header at the facility malfunctioned allowing the release of fluid. The header is located on the backside of the facility. The header has been repaired.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 320bbbls were release from the inlet header and we were able to recover 280bbbls with a vacuum truck. The spill area is located on the backside of the facility. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title:	Senior Environmental Coordinator	Approval Date:	JAN 18 2013 Expiration Date:
E-mail Address:	jrusso@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	01/10/2013	Phone:	432-212-2399

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN: February 18, 2013**

2RP-1508

Bratcher, Mike, EMNRD

From: Joshua Russo <jrusso@concho.com>
Sent: Thursday, January 10, 2013 1:50 PM
To: Bratcher, Mike, EMNRD
Cc: Ike Tavaréz (ike.tavaréz@tetrattech.com); Robert Grubbs (Robert.Grubbs@tetrattech.com); Tom Franklin (tom.k.franklin@tetrattech.com)
Subject: C-141 Initial Report - SRO 102 SWD
Attachments: SRO 102 SWD -- DATE OF RELEASE -- 12-31-2012.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred at our SRO 102 SWD on 12/31/2012. We plan to assess the spill area timely.

Thank you,

Joshua Russo

Sr. Environmental Coordinator

432.683.7443 (main)

432.685.4381 (direct)

432.212.2399 (cell)

jrusso@concho.com

Mailing Address:

One Concho Center

600 W. Illinios Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Wednesday, January 02, 2013 8:00 AM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo
Subject: SRO 102 SWD-Immediate Notification

Mr. Bratcher:

On 12/31/2012 at approximately 11:00 pm, a produced water release was discovered at the above-referenced facility. An estimated 320 bbls of produced water was released. The cause of the release is currently under investigation. We will get more details and follow up with a C-141 Report.

GPS coordinates, legal description, and driving directions below.

N 32 02.657 W 104 05.431

SRO 102 SWD

Unit G

Sec. 16 T26S R28E

Eddy County, NM

API 30-015-21398

From US 285 travel south to MM 5 (White City Road). Turn south at second cattle guard. Travel approximately 2 miles. Facility is on the south side of lease road.

Michelle Mullins

HSE Field Tech

2407 Pecos Avenue

P.O. Box 1630

Artesia, NM 88211-1630

Phone: (575)746-2010

Cell: (432) 934-1052

mmullins@conchoresources.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.