


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011
Appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NJM **W1303940453** OPERATOR Initial Report Final Report

Name of Company OXY USA 192463	Contact Chris Jones
Address 1502 W. Commerce Drive	Telephone No. 575-449-3337
Facility Name Samantha 31-6 Fed Com #1H	Facility Type Battery
Surface Owner	Mineral Owner
API No. 3001540050	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	31	18S	31E	990	S	450	W	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release OIL	Volume of Release 6 BBLS	Volume Recovered 0 BBLS
Source of Release SEPARATOR AT GATHERING FACILITY	Date and Hour of Occurrence 1-26-2013 0400AM	Date and Hour of Discovery 1-26-13 0400AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The dump valves on the separator were not operating properly and fluid went out the flare stack.		
Describe Area Affected and Cleanup Action Taken.* The soil in and outside of the battery were affected and after delineation and soil samples return a cleanup plan will be done in agreement with the NMOCD & BLM.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Chris Jones	Approved by Environmental Specialist	Signed By
Title: HES Specialist	Approval Date: FEB 08 2013	Expiration Date:
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 2-6-13 Phone: 575-449-3337	March 8, 2013	

* Attach Additional Sheets If Necessary

2RP-1548

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com
Sent: Wednesday, February 06, 2013 7:57 AM
To: Bratcher, Mike, EMNRD; jamos@blm.gov; jadeconstruction@live.com
Subject: FW:
Attachments: Document.pdf

I apologize for the tardy notification, I am just finding out about this myself. Here is the initial C-141.

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from
our ancestors; we borrow it from
our children." Chief Seattle

-----Original Message-----

From: Carlsbad_102 [mailto:Carlsbad_102@oxy.com]
Sent: Wednesday, February 06, 2013 7:55 AM
To: Jones, Christopher K
Subject:

Please open the attached document. This document was digitally sent to you using an HP Digital Sending device.

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com
Sent: Wednesday, February 06, 2013 7:31 AM
To: Bratcher, Mike, EMNRD; jamos@blm.gov
Cc: jadeconstruction@live.com
Subject: Samantha 31 #6

This is to inform you that Oxy Permian Primary had a spill of oil at the Samantha 31 #6 on January 29, 2013. Oxy released 6 bbls of oil, 0 bbls was recovered. Leak was due to failure in the dump valves on the heater treater. Oxy will do some initial remediation, a C-141 to follow. Jade Construction will delineate at a later date. REGULATORY LEASE # API 30-015-40050 SECT 31 T18S R31E OFF 222/SHUGART RD TURN WEST ON GRUBBS RD GO 2.5 MILE, TURN SOUTH GO 1.5 MILE TO BATTERY

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle