


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

njmw1304237619 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	F.M ROBINSON #001	Facility Type	TANK BATTERY
Surface Owner	STATE	Mineral Owner	
		Lease No. (API#) 30-015-22037	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	27	17S	29E					EDDY

Latitude 32.8077 Longitude 104.0690

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	30bbls oil 180bbls produced water	Volume Recovered	29bbls 176bbls produced water
Source of Release	Produced water tank	Date and Hour of Occurrence	01/31/2013	Date and Hour of Discovery	01/31/2013 1:30p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Michelle Mullins	Date and Hour	02/1/2013 8:20a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A power outage occurred causing the high level alarm to fail, allowing the water tank to overflow at the facility. Power has been restored to the facility.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 210bbls of produced fluid were released into the lined facility. We were able to recover 205bbls of fluid with a vacuum truck. The majority of the release remained inside the facility walls; some of the fluid overflowed the dike walls and flowed into the adjacent pasture area. All free fluid has been recovered. Tetra Tech will sample the spill site area in the pasture to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By
Title:	Senior Environmental Coordinator	Approval Date:	FEB 11 2013
E-mail Address:	jrusso@concho.com	Expiration Date:	
Date:	02/11/2013	Phone:	432-212-2399
		Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

March 11, 2013

2RP-1551

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Friday, February 01, 2013 7:20 AM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo
Subject: F.M. Robinson State #1 SWD-Immediate Notification

Mr. Bratcher:

At approximately 1:00 p.m. on 1/31/2013, a produced fluid release was discovered at the above-referenced facility. The fluid that was contained was inside the battery which is lined with 40 mil. Some fluid was released onto the pad and the pasture. An estimated 210 bbls of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report.

N 32 48.463 W 104 04.149

F.M. Robinson State #1 SWD
1850'FNL & 660 FWL
27-T17S R29E
Eddy County, NM
B-7596
API 30-015-22037

Take Highway 82 from Artesia east to Valley Gas Road. Turn south. Travel .7 miles. Turn east. Road dead ends at location.

Michelle Mullins
HSE Field Tech
2407 Pecos Avenue
P.O. Box 1630
Artesia, NM 88211-1630
Phone: (575)746-2010
Cell: (432) 934-1052
mmullins@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.