

RECEIVED
FEB 01 2012
NMOCD ARTESIA

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised October 10, 2003
 Submit 1 Copy to appropriate District Office in
 accordance with 19.15.29 NMAC

Release Notification and Corrective Action

JMH **1304537252** **OPERATOR** Initial Report Final Report

Name of Company: Linn Operating 269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Friess Federal Battery - Turner B #92	Facility Type: WaterFlood

Surface Owner: BLM	Mineral Owner: BLM	API No.: 3001526596
--------------------	--------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	20	17S	31E	1305	South	1350	West	Eddy

Latitude: N 32 49' 30.0" Longitude: W 103 53' 52.9"

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 3	Volume Recovered: 0
Source of Release: Valve	Date and Hour of Occurrence: 1/24/2012 10:00am	Date and Hour of Discovery: 01/24/2012 10:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher- NM OCD Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 01/24/2012 3:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: 3" check valve at header just north of injection line, valves blew hole due to corrosion. Shut down transfer pump and closed valves replaced check valve with new.

Describe Area Affected and Cleanup Action Taken.* : Further remedial action pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Joe Hernandez</i>	OIL CONSERVATION DIVISION
Printed Name: Joe Hernandez	Approved by District Supervisor: <i>Mike Bratcher</i> Signed By
Title: Production Foreman	Approval Date: FEB 14 2013 Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval: Attached <input type="checkbox"/>
Date: 02/01/2012 Phone: 575-942-9492	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:

* Attach Additional Sheets If Necessary

2RP-1558

March 14, 2013

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]
Sent: Wednesday, February 01, 2012 1:43 PM
To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)
Cc: Daniel Frick
Subject: Linn- Rev Initial C-141 Friess Fed Battery- Turner B #92
Attachments: Friess Fed Battery- Turner B 92.pdf

Please find revised copy of the Initial C-141 for the above referenced location.

Thank you,

Theresa McCracken

LINN Operating
2130 W. Bender Blvd
Hobbs, NM 88240
(575)738-1739
tmccracken@linnenergy.com

Warren, JeanMarie, EMNRD

From: Warren, JeanMarie, EMNRD
Sent: Tuesday, February 12, 2013 9:19 AM
To: 'tmccracken@linenergy.com'
Subject: 3 releases from Linn


Theresa,

Here is my email address. And per our conversation I will note that these releases for the API's 30-015-26596, and 30- will have **no** recoveries for the 3 barrel releases dated on 1/24/2012.

*Jean-Marie Warren
Business Operations Specialist
NM-OCD, Artesia
District II
811 S. First St.
Artesia, NM 88210
(575) 748-1283 ext. 101*

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Linn Operating	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Friess Federal Battery - Turner B #92	Facility Type: WaterFlood
Surface Owner: BLM	Mineral Owner: BLM
API No.: 3001526596	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	20	17S	31E	1305	South	1350	West	Eddy

Latitude: N 32 49' 30.0" Longitude: W 103 53' 52.9"

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 3	Volume Recovered: 3
Source of Release: Valve	Date and Hour of Occurrence: 1/24/2012 10:00am	Date and Hour of Discovery: 01/24/2012 10:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher- NM OCD Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 01/24/2012 3:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: 3" check valve at header just north of injection line, valves blew hole due to corrosion. Shut down transfer pump and closed valves replaced check valve with new.		
Describe Area Affected and Cleanup Action Taken.* : Further remedial action pending..		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Approved by District Supervisor:	
Title: Production Foreman	Approval Date:	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 02/01/2012	Phone: 575-942-9492	

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]
Sent: Wednesday, February 01, 2012 10:09 AM
To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)
Cc: Daniel Frick
Subject: Linn- Initial C-141 Friess Fed Battery- Turner B #92
Attachments: Friess Fed Battery- Turner B #92.pdf

Please find attached the Initial C-141 for the above referenced location.

Thank you,

Theresa McCracken

LINN Operating

2130 W. Bender Blvd

Hobbs, NM 88240

(575)738-1739

tmccracken@linnenergy.com