

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1305346221

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	J. CLEO THOMPSON <i>11181</i>	Contact	SHELLY BILBERRY
Address	325 N. ST PAUL, STE. 4300 DALLAS, TX 75201	Telephone No.	(432)550-8887
Facility Name	WEST SQUARE LAKE WELL 3	Facility Type	FEDERAL
Surface Owner	Mineral Owner	BLM API No. 30-015-04075	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	4	17S	60E 30E	660	NORTH	1980	EAST	EDDY

Latitude 32.869034476986 Longitude -103.974969595956

NATURE OF RELEASE

Type of Release	LEAK	Volume of Release	< 1 BBL	Volume Recovered	0
Source of Release	FLOWLINE	Date and Hour of Occurrence		Date and Hour of Discovery	01/15/2013
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	TIM GUMM	Date and Hour	01/16/2013		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*	N/A				
Describe Cause of Problem and Remedial Action Taken.*	LEAK IN FLOWLINE, REPAIRED FLOWLINE AND REMEDIATED CONTAMINATED SOIL WITH NEW SOIL TO CONTAIN AREA.				
Describe Area Affected and Cleanup Action Taken.*	AFFECTED AREA LESS THAN 1/4 MILE, REMEDIATION OF TOP SOIL, GRATING AND RESURFACING WITH NEW SOIL/DIRT.				

RECEIVED
FEB 08 2013
NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Shelly Bilberry</i>	OIL CONSERVATION DIVISION	
Printed Name:	SHELLY BILBERRY	Approved by Environmental Specialist:	Signed By <i>Mike Brannon</i>
Title:	REGULATORY SPECIALIST	Approval Date:	FEB 22 2013
E-mail Address:	SBILBERRY@JCLEO.COM	Expiration Date:	
Date:	01/30/2013	Phone:	(432)550-8887

Conditions of Approval:
Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN: March 22, 2013**

Attached

2RP-1561

* Attach Additional Sheets If Necessary

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company J. CLEO THOMPSON	Contact SHELLY BILBERRY
Address 325 N. ST PAUL, STE. 4300 DALLAS, TX 75201	Telephone No. (432)550-8887
Facility Name WEST SQUARE LAKE WELL 3	Facility Type FEDERAL

Surface Owner	Mineral Owner BLM	API No. 30-015-04075
---------------	-------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	4	17S	60E	660	NORTH	1980	EAST	EDDY


Latitude 32.869034476986 Longitude -103.974969595956

NATURE OF RELEASE

Type of Release LEAK	Volume of Release < 1 BBL	Volume Recovered 0
Source of Release FLOWLINE	Date and Hour of Occurrence	Date and Hour of Discovery 01/15/2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	

By Whom? TIM GUMM	Date and Hour 01/16/2013
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*
LEAK IN FLOWLINE, REPAIRED FLOWLINE AND REMEDIATED CONTAMINATED SOIL WITH NEW SOIL TO CONTAIN AREA.

Describe Area Affected and Cleanup Action Taken.*
AFFECTED AREA LESS THAN 1/4 MILE, REMEDIATION OF TOP SOIL, GRATING AND RESURFACING WITH NEW SOIL/DIRT.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Shelly Bilberry</i>	OIL CONSERVATION DIVISION	
Printed Name: SHELLY BILBERRY	Approved by Environmental Specialist:	
Title: REGULATORY SPECIALIST	Approval Date:	Expiration Date:
E-mail Address: SBILBERRY@JCLEO.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/30/2013 Phone: (432)550-8887		

* Attach Additional Sheets If Necessary

19-Feb-13

Well Inspection History

API Number: **30-015-04075-00-00** Well Name & No.: **WEST SQUARE LAKE UNIT**
Operator: **J CLEO THOMPSON, DONNA KLEIN** District: **ARTESIA** County Name: **EDDY**
Field: **WEST SQUARE LAKE UNIT** Legal: **S: 4 T: 17S R: 30E**
Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
1/16/2013	Routine/Periodic	Normal Routine Activity	iTWG1301641		202	Y	
		Well pumping, Wellhead hardpan. Flowline leak . Release running down hill in the sand to the east of location .Small location ok . LOV- leak . Could not reach Company . Called office .Workable phone no. 432--550-8887 Advised operator to send in C_141 .					
6/1/2012	Routine/Periodic	Normal Routine Activity	iTWG1215332		202		
		Well pumping, wellhead hqardpan. Offside casing valve open. Small location ok .					
12/14/2011	Routine/Periodic	Normal Routine Activity	iREH1134828		214		
		OK. All Equipment and Location in Good Shape. PJO.					
12/28/2010	Routine/Periodic	Normal Routine Activity	iTWG1036234		202		
		Well pumping.Offside casing valve open. Wellhead hardpan and small location stain. Equipment ok.					
3/25/2010	Routine/Periodic	Normal Routine Activity	iKMW1008434		215		
		oK. All Equipment and Location, pumping, historical contamination at wellhead and across location					
4/13/2009	Routine/Periodic	Normal Routine Activity	iTWG0910347		202		
		WELL PUMPING. WELL ASIGN LOSE. LARGE AREA OF VHIstorAL HARD PAN . CASING VALVE OPEN.					
5/1/2008	Routine/Periodic	Normal Routine Activity	iREH0812246		214		
		oK. All Equipment and Location in Good Shape. Gang truck on location.					
11/3/2004	Routine/Periodic	Normal Routine Activity	iPCH0430843		210		
		OK. All Equipment and Location in Good Shape.					
2/2/2000	Routine/Periodic	Normal Routine Activity	iMCS0000933		205		
		All Equipment and Location in Very Good Shape.					

Total Inspections Performed: 9