


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*njm* 1305352806 OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Myox 21 State Com #9H	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-37416

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	21	25S	28E					Eddy

Latitude 32 06.616 Longitude 104 05.958

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	18bbbls	Volume Recovered	15bbbls
Source of Release	FWKO	Date and Hour of Occurrence	02/03/2013	Date and Hour of Discovery	02/03/2013 12:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A hole developed in the water dump valve at the FWKO. The old valve has been replaced with a new valve.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 18bbbls were released from the water dump valve at the FWKO and we were able to recover 15bbbls with a vacuum truck. The entire release was contained inside the lined facility at the Myox 21 State Com #9H Tank Battery. All free fluids have been recovered. Any contaminated gravel has been removed, the liner has been washed, and we have replaced with clean gravel as necessary. This facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:					
Printed Name:	Josh Russo	OIL CONSERVATION DIVISION			
Title:	Senior Environmental Coordinator	Approved by District Supervisor:	Signed By		
E-mail Address:	jrusso@concho.com	Approval Date:	FEB 22 2013	Expiration Date:	
Date:	02/14/2013	Phone:	432-212-2399	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-1562

## Bratcher, Mike, EMNRD

---

**From:** Joshua Russo <jrusso@concho.com>  
**Sent:** Thursday, February 14, 2013 3:55 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Robert Grubbs  
**Subject:** C-141 Initial/Final Report - Myox 21 State Com #9H  
**Attachments:** MYOX 21 STATE COM #9H -- DATE OF RELEASE -- 02-03-2013.pdf

Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred inside the lined facility at our Myox 21 State Com #9H Tank Battery.

Thank you,

### **Joshua Russo**

Sr. Environmental Coordinator

432.683.7443 (main)

432.685.4381 (direct)

432.212.2399 (cell)

[jrusso@concho.com](mailto:jrusso@concho.com)

*Mailing Address:*

One Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.