


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*nJMW 1305630303* OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	OCHO CINCO COM #1H	Facility Type	TANK BATTERY
Surface Owner	FEDERAL	Mineral Owner	
		Lease No.(API#) 30-015-37614	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	8	26S	29E					EDDY

Latitude 32.0623 Longitude 103.9985

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	19bbls
Source of Release	3" transfer hose	Date and Hour of Occurrence	02/06/2013	Date and Hour of Discovery	02/06/2013 3:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A truck driver was transferring fluid at the facility; the truck driver's hose was not secured properly causing the fluid to be released in the lined facility.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbls were released from an unsecured hose connection. We were able to recover 19bbls with a vacuum truck. The release occurred inside the lined facility. All the fluid was contained inside the walls of the tank battery. All free fluid has been recovered. Contaminated gravel has been removed from inside the facility and we have replaced with fresh gravel as necessary. The facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:		<b>OIL CONSERVATION DIVISION</b>			
Printed Name: Josh Russo		Approved by District Supervisor:			
Title: Senior Environmental Coordinator		Approval Date: FEB 25 2013		Expiration Date:	
E-mail Address: jrusso@concho.com		Conditions of Approval:			Attached <input type="checkbox"/>
Date: 02/19/2013 Phone: 432-212-2399					

\* Attach Additional Sheets If Necessary

*2RP-1564*

**Bratcher, Mike, EMNRD**

---

**From:** Joshua Russo <jrusso@concho.com>  
**Sent:** Tuesday, February 19, 2013 12:29 PM  
**To:** Bratcher, Mike, EMNRD; Jim Amos office (jamos@blm.gov)  
**Cc:** Robert Grubbs  
**Subject:** C-141 Initial/ Final Report - Ocho Cinco Federal Com #1H Tank Battery  
**Attachments:** OCHO CINCO COM #1H TANK BATTERY -- DATE OF RELEASE -- 02-06-2013.pdf

Gentlemen,

Please see attached the C-141 Initial/Final Report for a release that occurred at our Ocho Cinco Federal Com #1H Tank Battery on 02/06/2013. This is a lined facility.

Thank you,

**Joshua Russo**

Sr. Environmental Coordinator

432.683.7443 (main)

432.685.4381 (direct)

432.212.2399 (cell)

[jrusso@concho.com](mailto:jrusso@concho.com)

*Mailing Address:*

One Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.