

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OGD**  
**OCT 22 2012**

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**RECEIVED** Release Notification and Corrective Action

**OPERATOR**

Initial Report  Final Report

Name of Company: XTO Energy, Inc	Contact: Dean Ericson
Address: 200 N Loraine, Suite 800, Midland, TX 79701	Telephone No.: 432-524-5673 (Office)
Facility Name: Southwest Royalties Inc	Facility Type: Tank Battery

Surface Owner: Eidson Ranch	Mineral Owner: State of New Mexico	Lease No.: 97887
-----------------------------	------------------------------------	------------------

**LOCATION OF RELEASE** *NEAREST WELL STATE UU COM #1 30-025-24661*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	7	17S	35E					Lea

Latitude 32.852183° Longitude -103.501633°

**NATURE OF RELEASE**

Type of Release: Crude Oil	Volume of Release: 15 barrels	Volume Recovered: 10 barrels
Source of Release: 4" Steel Gathering Line	Date and Hour of Occurrence	Date and Hour of Discovery: 10/16/12 1545
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
*awa @ 70'*

Describe Cause of Problem and Remedial Action Taken.\*  
Plane discovered a leak on the Southwest Royalty Battery - 4" Steel Gathering Line. XTO personal were notified, and the following remedial actions were taken: 4" steel gathering was shut-in and a flowline clamp installed. Vacuum Truck was dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.\*  
Approx. area affected 4,430 sq/ft area of pasture/grassland land. Following clean-up actions have and will be taken:  
1. Vacuum truck dispatched to recover standing fluid  
2. Contaminated soil will be removed and disposed off-site.  
3. Soil samples will be obtained to verify compliance with NMOCD remediation requirements.  
4. Soil will be replaced upon approval from land-owner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dean D. Ericson</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dean D. Ericson	<i>Jeffrey Yelking</i> Approved by District Supervisor: <b>Environmental Specialist</b>	
Title: EH&S, Regulatory and Compliance	Approval Date: <i>10/22/12</i>	Expiration Date: <i>12/22/12</i>
E-mail Address: <u>Dean_Ericson@xtoenergy.com</u>	Conditions of Approval: <b>SUBMIT FINAL C-141 BY 12/22/12</b>	Attached <input type="checkbox"/>
Date: 10/18/2012 Phone: 432-524-5673	<b>IRP-03-13-2907</b>	

\* Attach Additional Sheets If Necessary

**MAR 06 2013**