

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 13070 33093 OPERATOR Initial Report Final Report

Name of Company	BTA Oil Producers LLC <i>260297</i>	Contact	Pam Inskeep
Address	104 S. Pecos, Midland, TX 79701	Telephone No.	(432) 682-3753
Facility Name	Pardue -D-, 8808 JV-P	Facility Type	Well

Surface Owner	Antonio & Gloria Onsurez	Mineral Owner	Antonio & Gloria Onsurez	Lease No.	
---------------	--------------------------	---------------	--------------------------	-----------	--


LOCATION OF RELEASE

API: 30-015-26406

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	11	23S	28E	990	North	660	West	Eddy

NATURE OF RELEASE

Type of Release	Minor, produced water, sheen of oil	Volume of Release est	30 bbls	Volume Recovered	25 bbls
Source of Release	water tank overflowed	Date and Hour of Occurrence	3/4/2013	Date and Hour of Discovery	08:30 a.m
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD, Mike Bratcher (msg)		
By Whom?	Pam Inskeep, BTA	Date and Hour	3/4/2013, 1:00 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	---		



If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Transfer pump malfunctioned, allowed water tank to overflow. All fluid released was contained within the dike. Vacuum up all fluid possible and dispose of at R360 disposal facility. Repaired transfer pump. Will dig out contaminated soil, dispose of at R360, and replace with clean soil from a nearby source.

Describe Area Affected and Cleanup Action Taken.*
See above explanation

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Pam Inskeep</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name:	Pam Inskeep	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title:	Regulatory Administrator	Approval Date:	MAR 11 2013
Date:	03/04/2013	Expiration Date:	
Phone:	(432) 682-3753	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN: April 11, 2013** *2RP-1579*

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

copy

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	BTA Oil Producers LLC	Contact	Pam Inskeep
Address	104 S. Pecos, Midland, TX 79701	Telephone No.	(432) 682-3753
Facility Name	Pardue -D-, 8808 JV-P	Facility Type	Well

Surface Owner	Antonio & Gloria Onsurez	Mineral Owner	Antonio & Gloria Onsurez	Lease No.	
---------------	--------------------------	---------------	--------------------------	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	11	23S	28E	990	North	660	West	Eddy

NATURE OF RELEASE

Type of Release	Minor, produced water, sheen of oil	Volume of Release est	30 bbls	Volume Recovered	25 bbls
Source of Release	water tank overflowed	Date and Hour of Occurrence	3/4/2013	Date and Hour of Discovery	08:30 a.m
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD, Mike Bratcher (msg)		
By Whom?	Pam Inskeep, BTA	Date and Hour	3/4/2013, 1:00 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	---		

RECEIVED
MAR 08 2013
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Transfer pump malfunctioned, allowed water tank to overflow. All fluid released was contained within the dike. Vacuum up all fluid possible and dispose of at R360 disposal facility. Repaired transfer pump. Will dig out contaminated soil, dispose of at R360, and replace with clean soil from a nearby source.

Describe Area Affected and Cleanup Action Taken.*
See above explanation

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Pam Inskeep</i>	OIL CONSERVATION DIVISION	
Printed Name:	Pam Inskeep	Approved by District Supervisor:	
Title:	Regulatory Administrator	Approval Date:	Expiration Date:
Date:	03/04/2013	Phone:	(432) 682-3753
Conditions of Approval:			Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary