

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
MAR 08 2013
NMOCD ARTESIA
Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JM 1307040625
OPERATOR Initial Report Final Report
 Name of Company **COG OPERATING LLC 229137** Contact **Pat Ellis**
 Address **600 West Illinois Avenue, Midland, TX 79701** Telephone No. **432-230-0077**
 Facility Name **Y ENERGY STATE COM #001H** Facility Type **TANK BATTERY**
 Surface Owner **STATE** Mineral Owner _____ Lease No. (API#) **30-015-36033**


LOCATION OF RELEASE

Unit Letter L	Section 32	Township 18S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County EDDY
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude **32.70289** Longitude **103.99947**

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 15bbls	Volume Recovered 14bbls
Source of Release Check valve	Date and Hour of Occurrence 02-26-2013	Date and Hour of Discovery 02-26-2013 2:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The swedge and the gauge blew out of the check valve going to the water transfer pump inside the facility. The check valve has been replaced.		
Describe Area Affected and Cleanup Action Taken.* Initially 15bbls of produced water were released from a check valve where the swedge and gauge blew out of. The check valve was going to the water transfer pump inside the facility. We were able to recover 14bbls with a vacuum truck. The release was completely contained inside the lined facility walls of the tank battery. All free fluid has been recovered. Any contaminated gravel has been removed and we have replaced with fresh gravel as necessary. The facility has been returned to its prior condition.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Josh Russo	Approved by District Supervisor: _____	Signed By: 
Title: Senior Environmental Coordinator	Approval Date: MAR 11 2013	Expiration Date: _____
E-mail Address: jrusso@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 03-08-2013	Phone: 432-212-2399	

* Attach Additional Sheets If Necessary

2RP-1582

Bratcher, Mike, EMNRD

From: Joshua Russo <jrusso@concho.com>
Sent: Friday, March 08, 2013 2:47 PM
To: Bratcher, Mike, EMNRD
Cc: Robert Grubbs
Subject: C-141 Initial/Final Report - Y Energy State #001H Tank Battery
Attachments: Y ENERGY STATE COM #001H TANK BATTERY -- DATE OF RELEASE -- 02-26-2013.pdf

Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred on 02/26/2013 at our Y Energy State #001H Tank Battery. This is a lined facility.

Thank you,

Joshua Russo

Sr. Environmental Coordinator

432.683.7443 (main)

432.685.4381 (direct)

432.212.2399 (cell)

jrusso@concho.com

Mailing Address:

One Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.