

I & F

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

JMW 130704204 #22805 OPERATOR Initial Report Final Report

Name of Company	AMERICO ENERGY RESOURCES	Contact	GLENN BERTRAND
Address	7575 SAN FELICE, 200, HOUSTON, TX 77063	Telephone No.	713-984-9700
Facility Name	EAST SHURT # 61	Facility Type	PRODUCING WELL
Surface Owner	Mineral Owner		API No. 30-015-28202

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	35	18-S	31E	2310	FNL	865	FEL	RODGY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	PRODUCED OIL	Volume of Release	1.5 bbl	Volume Recovered	1.5 bbl
Source of Release	STUFFING BOX GLAND	Date and Hour of Occurrence	3-1-13	Date and Hour of Discovery	3-1-13 2PM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required				
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If a Watercourse was Impacted, Describe Fully.*					

RECEIVED
MAR 08 2013
NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*
PACKING IN STUFFING BOX @ POLISHED ROD STARTED LEAKING WHEN WELL IS ON CYCLE. PUMPER FOUND SEALING WELL, KILLED POWER & CALLED CLEAN UP CREW.

Describe Area Affected and Cleanup Action Taken.*
IMMEDIATELY AREA NEXT TO PUMPING WELL WAS AFFECTED. LEASE CREW CLEANED AREA. MATERIAL WAS COLLECTED & SENT TO R-360 SOLUTIONS SITE FOR DISPOSAL. STUFFING BOX PACKING WAS REPLACED. PUMPER FAILED TO NOTIFY AMERICO'S OFFICE & HAS BEEN SPOKEN TO!

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Accepted for record	NMOCD	
Title:	Approved by Environmental Specialist:	MAR 11 2013	
E-mail Address:	Approval Date:	Expiration Date:	
Date:	Conditions of Approval:	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1583

3/4/13 After
cleanup
EAB

M AmeriCo Energy Resources **CO**
LAST SURVIVOR UNIT #01
SECTION 35, T18S, R31E
2310' FNL & -865' FEL
NM-10191
EDDY COUNTY, NEW MEXICO

