

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*JMK/309439698* OPERATOR  Initial Report  Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Lupe Carrasco
Address 104 S. 4 <sup>TH</sup> Street	Telephone No. 575-748-1471	
Facility Name NDDUP Unit #54	API Number 30-015-25645	Facility Type Plugged & Abandoned Well

Surface Owner Federal	Mineral Owner Federal	Lease No.
--------------------------	--------------------------	-----------


**LOCATION OF RELEASE**

Unit Letter B	Section 19	Township 19S	Range 25E	Feet from the 660	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.6518200 Longitude 104.5214100

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 20 B/PW	Volume Recovered 5 B/PW
Source of Release Line Break	Date and Hour of Occurrence 3/15/13	Date and Hour of Discovery 3/15/13
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (email)	
By Whom? Lupe Carrasco	Date and Hour 3/15/13 3:35 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		



Describe Cause of Problem and Remedial Action Taken.\*  
Water line break due to normal wear and age of line, in addition to expansion of the line due to cool nights and warm days. Vacuum truck dispatched to recover produced water. Crew called to repair line.

Describe Area Affected and Cleanup Action Taken.\*  
An approximate area of 2' X 45'. Impacted soils to be scraped up and taken to an NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX, Chlorides will be run for documentation. If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted.  
**Depth to Ground Water: >100' (approximately 225', Section 19-T19S-R25E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lupe Carrasco</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Lupe Carrasco	Approved by District Supervisor: Signed By <i>Mike Bratcher</i>	
Title: Environmental Regulatory Agent	Approval Date: <b>APR 04 2013</b>	Expiration Date:
E-mail Address: <b>lcarrasco@yatespetroleum.com</b>	Conditions of Approval: Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION</b>	Attached <input type="checkbox"/>
Date: Monday, March 25, 2013 Phone: 575-748-1471	<b>PROPOSAL NO LATER THAN:</b> <i>May 4, 2013</i>	

*2RP-1594*

\* Attach Additional Sheets If Necessary

## Bratcher, Mike, EMNRD

---

**From:** Lupe Carrasco <LCarrasco@yatespetroleum.com>  
**Sent:** Friday, March 15, 2013 3:35 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Amanda Trujillo; Amber Cannon; Bob Asher; Katie Parker  
**Subject:** Release(NDDUP Unit #54)

Yates Petroleum Corporation is reporting a release at the following location (3/15/2013).

NDDUP Unit #54  
30-015-25645  
Section 19, T19S-R25E  
Eddy County, New Mexico

Released: Approximately 15 B/PW; Recovered: Unknown at this time.

Release was from a water line break. Line has been isolated and wells shut in. Vacuum truck has been dispatched. One-call placed for line repair.

A Form C-141 Initial/Final Report will be submitted with complete information.

Thank you.

Lupe Carrasco  
*Environmental Regulatory Agent*  
Yates Petroleum Corporation  
Office: (575) 748-4350  
Fax: (575) 748-4131  
Cell: (575) 513-9074

---

**This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.**

---