


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JTW 1309541502

OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	CLUSTER STATE COM #001H	Facility Type	TANK BATTERY

Surface Owner STATE Mineral Owner Lease No. (API#) 30-015-37547

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	16	26S	27E					EDDY

Latitude 32.04866 Longitude 104.20266

NATURE OF RELEASE

Type of Release Oil	Volume of Release 6bbls	Volume Recovered 3bbls
Source of Release Tank over flowed	Date and Hour of Occurrence 03-11-2013	Date and Hour of Discovery 03-11-2013 8:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Due to both and alarm failure and haul trucks not being available to haul oil, the oil tank overflowed. Have haul trucks arrive early and replaced the transducers on the alarm.		
Describe Area Affected and Cleanup Action Taken.* Initially 6bbbs of oil were released from the oil tank inside the tank battery due to oil trucks running late and alarm failure. We were able to recover 3bbbs of oil with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we have replaced with fresh gravel as necessary. This location has been returned to its prior condition.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Josh Russo	Approved by District Supervisor:	Signed By:
Title: Senior Environmental Coordinator	Approval Date: APR 05 2013	Expiration Date:
E-mail Address: jrusso@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 03-20-2013 Phone: 432-212-2399		

* Attach Additional Sheets If Necessary

2RP-1597

Accepted for record
NMOCD

Accepted for record
NMOCD

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, March 20, 2013 3:17 PM
To: Bratcher, Mike, EMNRD
Cc: Tavarez, Ike; tom.k.franklin@tetrattech.com; Joshua Russo
Subject: C-141 Initial/Final Report - Cluster State Com #001 TB
Attachments: CLUSTER STATE COM #001H TANK BATTERY -- DATE OF RELEASE -- 03-11-2013.pdf

Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred inside the lined facility at our Cluster State Com #001 TB on 03/11/2013.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com

Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.