


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

njmw 1310629812

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	PINTO 29 FEDERAL #001	Facility Type	TANK BATTERY
Surface Owner	FEDERAL	Mineral Owner	
		Lease No. (API#) 30-015-31956	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	29	17S	30E					EDDY

Latitude 32.81194 Longitude 103.99204

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	15bbls	Volume Recovered	14bbls
Source of Release	Steel line from circulating pump.	Date and Hour of Occurrence	04-03-2013	Date and Hour of Discovery	04-03-2013 3:30pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A hole had developed in a steel line going from the circulating pump to the heater treater. The steel line has been replaced.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 15bbls of oil were released from a steel line that had developed a hole going from the circulating pump to the heater treater. We were able to recover 14bbls with a vacuum truck. The release was contained within the inside of the facility walls. All free fluids have been recovered. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature: *Josh Russo*
Printed Name: Josh Russo
Title: Senior Environmental Coordinator
E-mail Address: jrusso@concho.com
Date: 4-5-2013 Phone: 432-212-2399

Approved by District Supervisor: Signed By *Mike Brannon*
Approval Date: **APR 16 2013** Expiration Date:
Conditions of Approval: Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**
Attached

* Attach Additional Sheets If Necessary

May 16, 2013

2RP-1621

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, April 11, 2013 8:05 AM
To: Bratcher, Mike, EMNRD; Amos, James <jamos@blm.gov> (jamos@blm.gov)
Cc: Tavaréz, Ike; tom.k.franklin@tetrattech.com; Joshua Russo
Subject: C-141 Initial Report - Pinto 29 Federal #001 Tank Battery
Attachments: PINTO 29 FEDERAL #001 -- DATE OF RELEASE -- 04-03-2013.pdf

Gentlemen,

Please see attached the C-141 Initial Report for a release that occurred on 04-03-2013 at our Pinto 29 Federal #001 Tank Battery in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com

Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Amos, James <jamos@blm.gov>
Sent: Friday, April 12, 2013 1:04 PM
To: Robert Grubbs
Cc: Bratcher, Mike, EMNRD; Tavarez, Ike; tom.k.franklin@tetrattech.com; Joshua Russo
Subject: Re: C-141 Initial Report - Pinto 29 Federal #001 Tank Battery

Thanks, Mike Burton will be the BLM rep on this event.

On Thu, Apr 11, 2013 at 8:04 AM, Robert Grubbs <RGrubbs@concho.com> wrote:

Gentlemen,

Please see attached the C-141 Initial Report for a release that occurred on 04-03-2013 at our Pinto 29 Federal #001 Tank Battery in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.

Sr. Environmental Coordinator

432.683.7443 (main)

432.818.2369 (direct)

432.661.6601 (cell)

rgrubbs@concho.com

Mailing Address:

One Concho Center

600 W. Illinois Avenue


Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	PINTO 29 FEDERAL #001	Facility Type	TANK BATTERY
Surface Owner	FEDERAL	Mineral Owner	
		Lease No. (API#)	30-015-31956

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	29	17S	30E					EDDY

Latitude 32.81194 Longitude 103.99204

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	15bbls	Volume Recovered	14bbls
Source of Release	Steel line from circulating pump.	Date and Hour of Occurrence	04-03-2013	Date and Hour of Discovery	04-03-2013 3:30pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A hole had developed in a steel line going from the circulating pump to the heater treater. The steel line has been replaced.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 15bbls of oil were released from a steel line that had developed a hole going from the circulating pump to the heater treater. We were able to recover 14bbls with a vacuum truck. The release was contained within the inside of the facility walls. All free fluids have been recovered. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:		Approved by District Supervisor:	
Printed Name:	Josh Russo	Approval Date:	Expiration Date:
Title:	Senior Environmental Coordinator	Conditions of Approval:	
E-mail Address:	jrusso@concho.com	Attached <input type="checkbox"/>	
Date:	4-5-2013	Phone:	432-212-2399

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, April 17, 2013 10:39 AM
To: Bratcher, Mike, EMNRD; Amos, James <jamos@blm.gov> (jamos@blm.gov)
Cc: Tavarez, Ike; tom.k.franklin@tetrattech.com; Joshua Russo
Subject: C-141 Initial Report - Pinto 29 Federal #001 Tank Battery
Attachments: PINTO 29 FEDERAL #001 -- DATE OF RELEASE -- 04-03-2013.pdf

Gentlemen,

Please see attached the C-141 Initial Report for a release that occurred on 04/03/2013 at our Pinto 29 Federal #001 Tank Battery in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator

432.683.7443 (main)

432.818.2369 (direct)

432.661.6601 (cell)

rgrubbs@concho.com

Mailing Address:

One Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.