

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
South St. Francis
Santa Fe, NM 87505

RECEIVED
APR 16 2013
ARTESIA

RECEIVED
APR 16 2013
NMOCD ARTESIA

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 30755257

OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Golden "D" Federal Well #4 Flow line	Facility Type: Exploration and Production
Release is 4630 ft. NW of well location in Section 8-21-29	

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-35636
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	8	21S	29E					Eddy

Latitude N 32.488680 Longitude W 104.008276

NATURE OF RELEASE

Type of Release Crude oil and produced water	Volume of Release 10 bbls oil and 10 bbls produced water	Volume Recovered 5 bbls total fluid
Source of Release 27/8" Flow line	Date and Hour of Occurrence 3/16/13 time unknown	Date and Hour of Discovery 3/16/13 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The flow developed a leak due to internal corrosion; the bad section of pipe was replaced.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 1440 sq. ft. of lease road and approximately 2700 ft. of pasture land. The free standing fluid was recovered with a vacuum truck and the saturated soil was scraped up, approximately 18 cubic yards of soil was hauled to Lea Lands for disposal. The impacted area will be remediated in accordance with the NMOCD and BLM spill remediation requirements for spills and releases.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Tony Savoie</i> Printed Name: Tony Savoie Title: Waste Management and Remediation Specialist E-mail Address: tasavoie@basspet.com Date: <i>4/16/13</i> Phone: 432-556-8730	OIL CONSERVATION DIVISION Approved by Environmental Specialist: Signed By <i>Mike Sanchez</i> Approval Date: APR 17 2013 Expiration Date: Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u><i>May 17, 2013</i></u>
--	--

Attached
2RP-1625

* Attach Additional Sheets If Necessary