


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JMW 1311331406

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 105 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Martha AIK Federal #1	API Number 30-015-26549	Facility Type Battery
Surface Owner Federal	Mineral Owner Federal	Lease No. NM-65417

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	11	22S	31E	330'	South	430'	East	Eddy

Latitude 32.39966 Longitude 103.74086

NATURE OF RELEASE

Type of Release Produced Water; Crude Oil	Volume of Release 850 B/PW; 33 B/O	Volume Recovered 650 B/PW; 20 B/O
Source of Release Water transfer pump	Date and Hour of Occurrence 4/18/2013; AM	Date and Hour of Discovery 4/18/2013, AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 4/19/2013; AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The discharge hose from a water transfer pump ruptured, releasing produced water and oil.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 36' X 100' (most of release occurred inside of the unlined bermed battery. Some of the water/oil escaped out of the berm to the south of the tanks). A vacuum truck was called to recover fluids, all wells to battery were shut in, tank valves were shut, and hose was repaired. A crew was called to do initial clean-up of the area, and all excavated soils will be disposed of at an approved NMOCD facility. Vertical and horizontal delineation samples will be taken and sent to a NMOCD approved facility. Depth to Ground Water: >100' (approximately 150', Section 11, T22S-R31E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Amber Cannon</i>	Approved by District Supervisor: Signed By <i>Mike Bratcher</i>	
Printed Name: Amber Cannon	Approval Date: APR 23 2013	Expiration Date:
Title: Environmental Regulatory Agent	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
E-mail Address: acannon@yatespetroleum.com	Attached <input type="checkbox"/>	
Date: Friday, April 19, 2013 Phone: 575-748-4111		

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
May 23, 2013 *ZRP-1631*

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Friday, April 19, 2013 8:20 AM
To: Bratcher, Mike, EMNRD; Dade, Randy, EMNRD; jamos@blm.gov
Cc: Amber Cannon; Katie Parker; Lupe Carrasco
Subject: Release (Martha AIK Federal #1)

Yates Petroleum Corporation is reporting a release at the following location (4/18/2013).

Martha AIK Federal #1 Battery
30-015-26549
Section 11, T22S-R31E
Eddy County, New Mexico

Released: Approximately 33 B/O & 850 B/PW; Recovered: Approximately 20 B/O & 650 B/PW.

Release was from a discharge hose on the water transfer pump ruptured. Wells and tanks shut in. Vacuum truck(s) were called and recovered remaining oil and produced water.

A Form C-141 Initial will be submitted with complete information.

Thank you.

Robert Asher

NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Bratcher, Mike, EMNRD

From: Amber Cannon <ACannon@yatespetroleum.com>
Sent: Friday, April 19, 2013 3:12 PM
To: Bratcher, Mike, EMNRD; Dade, Randy, EMNRD; jamos@blm.gov
Cc: Bob Asher; Katie Parker
Subject: RE: Release (Martha AIK Federal #1
Attachments: MarthaAIKFederal1_C141_04-18-13 Initial.pdf

Please find attached the Initial C-141 for the release mentioned below.

Thanks,

Amber Cannon

Environmental Regulatory Agent
Yates Petroleum Corporation
Office: (575) 748-4111
Cell: (575) 513-8799

From: Bob Asher
Sent: Friday, April 19, 2013 8:20 AM
To: (mike.bratcher@state.nm.us); (Randy.Dade@state.nm.us); jamos@blm.gov
Cc: Amber Cannon; Katie Parker; Lupe Carrasco
Subject: Release (Martha AIK Federal #1

Yates Petroleum Corporation is reporting a release at the following location (4/18/2013).

Martha AIK Federal #1 Battery
30-015-26549
Section 11, T22S-R31E
Eddy County, New Mexico

Released: Approximately 33 B/O & 850 B/PW; Recovered: Approximately 20 B/O & 650 B/PW.

Release was from a discharge hose on the water transfer pump ruptured. Wells and tanks shut in. Vacuum truck(s) were called and recovered remaining oil and produced water.

A Form C-141 Initial will be submitted with complete information.

Thank you.

Robert Asher

NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
