

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

njmw1314038799

OPERATOR

x Initial Report Final Report

Name of Company Mesquite SWD Inc. <i>161968</i>	Contact Clay L Wilson	
Address P.O. 1479 Carlsbad NM 88221	Telephone No. 575 706 1840	
Facility Name Big Eddy	Facility Type SWD Unload Station	
Surface Owner Blm/ Creamer	Mineral Owner	API No.30-015=05819

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	3	20S	31E	660	FSL	660	FEL	

Latitude *32.597007* Longitude *103.850615*

NATURE OF RELEASE


Type of Release Produced water	Volume of Release 30bbbs	Volume Recovered 15bbbs
Source of Release Hole in flow line	Date and Hour of Occurrence 3/11/13 11.00am	Date and Hour of Discovery 3/11/13 11.00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Poly line looked like it rub up against something while being installed. In the process of digging out the contaminated soil and hauling it to CRI		
Describe Area Affected and Cleanup Action Taken.* Ranch Land, Digging out contaminated and hauling to CRI		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

RECEIVED
MAY 14 2013
NMOCD ARTESIA

Signature: <i>Clay Wilson</i>	OIL CONSERVATION DIVISION	
Printed Name: Clay L Wilson	Approved by Environmental Specialist:	Signed By: <i>Mike Deaton</i>
Title: President	Approval Date: MAY 20 2013	Expiration Date:
E-mail Address: Claywilson@hotmail.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 5-13-13 Phone: 575 706 1840	June 20, 2013	<i>2RP-1652</i>

* Attach Additional Sheets If Necessary

Mesquite SWD, Inc. Big Eddy SWD #1 015-05819 P-3-20s-31E



Google earth

