


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JMW 1314040088

Name of Company		COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address		600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077		
Facility Name		HAMBONE FEE COM #001H	Facility Type	TANK BATTERY		
Surface Owner		FEDERAL	Mineral Owner		Lease No. (API#) 30-015-38980	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	05	26S	29E					EDDY

Latitude 32.06615 Longitude 104.01392

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	100bbbls	Volume Recovered	99bbbls
Source of Release	Bleeder valve on filter pot	Date and Hour of Occurrence	05-06-2013	Date and Hour of Discovery	05-06-2013 4:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	05-07-2013 4:45pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Bleeder valve was left open on filter pot after the water pump had been serviced. Shut the valve to prevent further release.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 100bbbls of produced water were released due to the filter pot valve being left after the water pump was serviced. We were able to recover 99bbbls of produced water with a vacuum truck. The spill was completely contained in a lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned, and we have replaced with fresh gravel as necessary. This facility has been returned to its prior condition.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	Signed By: <i>Mike Bratcher</i>
Title:	Senior Environmental Coordinator	Approval Date:	MAY 20 2013
E-mail Address:	rgrubbs@concho.com	Expiration Date:	
Date:	05-14-2013	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-661-6601		

* Attach Additional Sheets If Necessary

2RP-1653

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, May 15, 2013 12:46 PM
To: Bratcher, Mike, EMNRD
Cc: Amos, James <jamos@blm.gov> (jamos@blm.gov); Joshua Russo
Subject: C-141 Initial/Final Report - Hambone Fee Com #001H
Attachments: HAMBONE FEE COM #001H (TANK BATTERY) -- DATE OF RELEASE -- 05-06-2013.pdf

Gentlemen,

Please see attached the C-141 Initial / Final Report for a release that occurred at our Hambone Fee Com #001H on 05-06-2013. This is a lined facility.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com

Mailing Address:

One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Amos, James <jamos@blm.gov>
Sent: Wednesday, May 15, 2013 2:50 PM
To: Robert Grubbs
Cc: Bratcher, Mike, EMNRD; Joshua Russo
Subject: Re: C-141 Initial/Final Report - Hambone Fee Com #001H

This is an OCD site only. thanks

On Wed, May 15, 2013 at 12:46 PM, Robert Grubbs <RGrubbs@concho.com> wrote:

Gentlemen,

Please see attached the C-141 Initial / Final Report for a release that occurred at our Hambone Fee Com #001H on 05-06-2013. This is a lined facility.

Thank you,

Robert Grubbs Jr.

Sr. Environmental Coordinator

432.683.7443 (main)

432.818.2369 (direct)

432.661.6601 (cell)

rgrubbs@concho.com

Mailing Address:

One Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Tuesday, May 07, 2013 3:45 PM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo; Robert Grubbs
Subject: Hambone Fee Com #1H-Immediate Notification

Mr. Bratcher:

At approximately 4:00 p.m. on 5/06/2013, a produced fluid release was discovered at the above-referenced facility. The fluid was contained inside the battery which is lined with 40 mil. An estimated 100 bbls of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report.

N 32 deg 03'57.3", W 104 deg 00'50.4"

Hambone Fee Com #1H

Unit M, Sec. 5

T26S R29E

660' FSL & 330 FWL

Eddy County, NM

API 30-015-38980

South of Malaga on Highway 285, turn east at MM 4 (CR 725), travel approximately 3.4 miles. Battery is on the right.

Michelle Mullins

HSE Field Tech

2407 Pecos Avenue

P.O. Box 1630

Artesia, NM 88211-1630

Phone: (575)746-2010

Cell: (432) 934-1052

mmullins@conchoresources.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.