

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

REC-111
MAY 22 2013
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1314941264

Name of Company		COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address		600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077		
Facility Name		SKELLY UNIT #989	Facility Type	TANK BATTERY		
Surface Owner		FEDERAL	Mineral Owner		Lease No. (API#) 30-015-36498	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	23	17S	31E					EDDY

Latitude 32.82191 Longitude 104.84353

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	14bbls Oil 1bbl Produced water	Volume Recovered	13bbls Oil 1bbl Produced water
Source of Release	1" leaking valve	Date and Hour of Occurrence	05-09-2013	Date and Hour of Discovery	05-09-2013 2:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 1" valve was leaking by filling up containment and running over into lined dike. Replaced valve to prevent reoccurrence.

Describe Area Affected and Cleanup Action Taken.*

Initially 14bbls of produced fluids were released due to a leaking valve. We were able to recover 14bbls of produced fluids with a vacuum truck. The spill was completely contained inside the lined facility walls. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned, and we have replaced with fresh gravel as necessary. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	Signed By <i>Michelle Beaudoin</i>
Title:	Senior Environmental Coordinator	Approval Date:	MAY 29 2013
E-mail Address:	rgrubbs@concho.com	Expiration Date:	
Date:	05-17-2013	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-661-6601		

* Attach Additional Sheets If Necessary

ZRP-1665

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, May 22, 2013 10:49 AM
To: Bratcher, Mike, EMNRD; Amos, James <jamos@blm.gov> (jamos@blm.gov)
Cc: Joshua Russo
Subject: C-141 Initial/Final Report - Skelly Unit #989
Attachments: SKELLY UNIT #989 TANK BATTERY -- DATE OF RELEASE -- 05-09-2013.pdf

Gentlemen,

Please see attached the C-141 Initial / Final Report for a release that occurred at our Skelly Unit #989 on 05-09-2013. This is a lined facility.

Thank you,

Robert Grubbs, Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)

rgrubbs@concho.com

Mailing Address:

One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.