

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

use updated form

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1315051978

OPERATOR

Initial Report Final Report

Name of Company Devon Energy 6137	Contact Dan Suniga
Address P. O. Box 250 Artesia, NM 88211	Telephone No. 575-746-5555
Facility Name Todd 36M State No. 13	Facility Type Oil Well

*Please include
API #'s *

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

API #: 30-015-28815

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	36	23S	31E	1090	SOUTH	330	WEST	EDDY

NATURE OF RELEASE

Type of Release Oil/Produced Water	Volume of Release 6 oil/ 4 w	Volume Recovered 0/0
Source of Release Spill	Date and Hour of Occurrence 5/24/13 10:00pm	Date and Hour of Discovery 5/24/13 10:00pm

Was Immediate Notice Given?
 Yes No Not Required

If YES, To Whom? Mike Bratcher/OCD

By Whom? HUB PERRY ASST FOREMAN
Was a Watercourse Reached?
 Yes No

Date and Hour 5/24/13 10:00pm
If YES, Volume Impacting the Watercourse.

If a Watercourse was Impacted, Describe Fully.*

CEIVED

MAY 29 2013

N/A

ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

At the Todd 36-13 production location, a water transport driver ran over a steel flow line resulting in a spill of 6bbls of oil and 4bbls of produced water.

Describe Area Affected and Cleanup Action Taken.*

At the Todd 36-13 production location, a water transport driver ran over a steel flow line resulting in a spill of 6bbls of oil and 4bbls of produced water. The trucks were delivering fresh water to the Aldabra frac pond when one of them ran over the steel flow line connection. The company notified Devon PIC and arrangements were then made to shut the well in and attempt to pick up fluid. No fluid was recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Veronica Teel

Approved by

Printed Name: Veronica Teel

District Supervisor:

Signed By Mike Bratcher

Title: Field Admin Sr. Port

Approval Date: MAY 30 2013

Expiration Date:

Date: 5/28/13 Phone: (575) 748-9933

Conditions of Approval:

Attached

Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION

2RP-1669

PROPOSAL NO LATER THAN:

June 30 2013